

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 587971

**QUESTIONS**

|   |  |
|---|--|
| Operator:<br>BTA OIL PRODUCERS, LLC<br>104 S Pecos<br>Midland, TX 79701 | OGRID:<br>260297   |
|   | Action Number:<br>587971   |
|   | Action Type:<br>[NOTIFY] Notification Of Liner Inspection (C-141L) |

**QUESTIONS**

|                      |   |
|----------------------|---|
| <b>Prerequisites</b> |   |
| Incident ID (n#)     | nAPP2614228521                                    |
| Incident Name        | NAPP2614228521 NORTHRIDGE WEST CTB @ C-35-22S-34E |
| Incident Type        | Produced Water Release                            |
| Incident Status      | Notification Accepted                             |

|                                   |                     |
|-----------------------------------|---------------------|
| <b>Location of Release Source</b> |                     |
| Site Name                         | Northridge West CTB |
| Date Release Discovered           | 05/21/2026          |
| Surface Owner                     | State               |

|   |                                  |
|---|----------------------------------|
| <b>Liner Inspection Event Information</b>   |                                  |
| <i>Please answer all the questions in this group.</i>   |                                  |
| What is the liner inspection surface area in square feet  | 5,600                            |
| Have all the impacted materials been removed from the liner   | Yes                              |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 05/29/2026                       |
| Time liner inspection will commence   | 08:30 AM                         |
| Please provide any information necessary for observers to liner inspection                              | Carmona Resources – 432-813-8988 |
| Please provide any information necessary for navigation to liner inspection site                        | 32.352704,-103.443982            |

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 587971

**CONDITIONS**

|   |  |
|---|--|
| Operator:<br>BTA OIL PRODUCERS, LLC<br>104 S Pecos<br>Midland, TX 79701 | OGRID:<br>260297   |
|   | Action Number:<br>587971   |
|   | Action Type:<br>[NOTIFY] Notification Of Liner Inspection (C-141L) |

**CONDITIONS**

| Created By | Condition  | Condition Date |
|------------|--|----------------|
| adelaney   | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 5/26/2026      |