

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company <b>DC Energy</b>	Contact <b>Dan Johnson</b>
Address	Telephone No. <b>770-257-3715</b>
Facility Name <b>SWD #248</b>	Facility Type <b>Disposal</b>

Surface Owner <b>Willis Trust Fund</b>	Mineral Owner <b>Willis Trust Fund</b>	Lease No. <b>SWD #248</b>
--	--	---------------------------

**LOCATION OF RELEASE**

Unit Letter <b>J</b>	Section <b>33</b>	Township <b>2SS</b>	Range <b>37E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Lea</b>
----------------------	-------------------	---------------------	------------------	---------------	------------------	---------------	----------------	-------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release <b>Produced Water</b>	Volume of Release <b>130 ABL</b>	Volume Recovered <b>60-70 ABL</b>
Source of Release	Date and Hour of Occurrence <b>3:17</b>	Date and Hour of Discovery <b>3:17:11</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>8:15</b>	<b>8:15 am</b>
By Whom? <b>Dan Johnson</b>	Date and Hour <b>3:17:11</b>	<b>8:25 am</b>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully \*  
**None**

Describe Cause of Problem and Remedial Action Taken.\*  
**Unique water truck had rear seal blow out causing 130 ABLs to spill out onto ground on pad at Disposal - picked up 60-70 ABLs with Vacuum trucks**

Describe Area Affected and Cleanup Action Taken.\*  
**South side of pad was impacted and small area in pasture - Had backhoe scrape up and haul off to Sandwell for disposal. Sampled area all samples clean Hauled in 3 loads of cubic to Backfill area**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other, federal, state, or local laws and/or regulations.

Signature: <b>Jared Melancon</b>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jared Melancon</b>		Approved by District Supervisor: <b>Jeffrey Leeking</b>	
Title: <b>Operation Foreman</b>		Approval Date: <b>04/01/11</b>	Expiration Date: <b>—</b>
E-mail Address:		Conditions of Approval:	
Date: <b>4-1-11</b>	Phone: <b>861-770-1904</b>	Attached <input type="checkbox"/> <b>IRP-03-11-2693</b>	

\* Attach Additional Sheets If Necessary