

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-22621

Release Notification and Corrective Action

nMLB 1121329960

3080

OPERATOR

Initial Report Final Report

Name of Company	Buenett Oil Co. Inc.	Contact	Balton Matthews
Address	Box 198 Laca Hills NM 98255	Telephone No.	575-677-2313
Facility Name	Jackson B # 32	Facility Type	Inj. Well
Surface Owner	BLM	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	1	17	30	1980	South	1980	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Salt Water	Volume of Release	App. 20064	Volume Recovered	30643
Source of Release	Casing Leak	Date and Hour of Occurrence	7/4	Date and Hour of Discovery	7/5 9am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Brubaker - OCS Jim Amos - BLM		
By Whom?	Eddie Seay - Agent	Date and Hour	7/5 9:15 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED
JUL 11 2011
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Hole in casing causing injection water to come to surface, and into pattern shot in injection, vacuum up water, build emergency pit to catch water, also put track tank to hold water. Waiting on pulling unit to repair well.

Describe Area Affected and Cleanup Action Taken.*

Ran into pattern south + west; water pooled up in low spot approx 125 ft south. area (110x80) water soaked. Ran west in small drain, 204 ft wide approx 150 ft. All available water vacuumed up. (will file Work Plan for remediation)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Eddie W Seay</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>Eddie W Seay</u>		Approved by District Supervisor: <u>M/L Brubaker</u>	
Title: <u>Agent</u>		Approval Date: <u>8/1/2011</u>	Expiration Date:
E-mail Address: <u>seay06@laca.net</u>		Conditions of Approval:	
Date: <u>7/7/2011</u> Phone: <u>575-390-2454</u>		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: Remediation Proposal
Rec'd 7/14/2011

2 RP-803