

LEGEND:

- BENZENE GROUNDWATER EXCEEDANCE AREA
- MONITORING WELL
- RECOVERY WELL
- IRRIGATION WELL
- ABANDONED WELL

0 800 1,600 2,400 3,200 Feet

GRAPHIC SCALE

NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO

2011 ANNUAL GROUNDWATER REPORT

BENZENE CRITICAL GROUNDWATER SCREENING LEVEL EXCEEDANCE AREAS SECOND SEMIANNUAL EVENT 2011

ARCADIS

FIGURE 14

CITY: DIV/GROUP: DB: LD: PIC: PM: TM: TR:
Project (Project #)
Q:\NavajoRefiningArtesiaRefinery\Annual_GW_Report_2011\MXD\14_Benzene_SA2_2011.mxd - 3/15/2012 @ 3:18:59 PM