





LEGEND:

- NAPHTHALENE GROUNDWATER EXCEEDANCE AREA

- MONITORING WELL
- RECOVERY WELL
- IRRIGATION WELL
- ABANDONED WELL



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
2011 ANNUAL GROUNDWATER REPORT

NAPHTHALENE CRITICAL GROUNDWATER SCREENING LEVEL EXCEEDANCE AREAS SECOND SEMIANNUAL EVENT 2011