

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-05-29290

Release Notification and Corrective Action

NMLB1116757436

OPERATOR



Initial Report



Final Report

Name of Company Devon Energy <i>6137</i>	Contact Roy White, Foreman
Address 6488 Seven Rivers Hwy - P.O. Box 250	Telephone No. 575-748-5234
Facility Name Ore Ida 14 Federal #10	Facility Type

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------


LOCATION OF RELEASE

Unit Letter	Section 14	Township 24S	Range 29E	Feet from the 1780'	North/South Line FSL	Feet from the 860'	East/West Line FEL	County Eddy
-------------	----------------------	------------------------	---------------------	-------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------

Latitude - N32.21516 * Longitude - 103.94927

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 100 bbls	Volume Recovered 0
Source of Release Above Ground Poly Line was ran over	Date and Hour of Occurrence 05/11/11 - 10:00 pm	Date and Hour of Discovery 05-11-11 - 10:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos	
By Whom? Roy White, Foreman	Date and Hour 05-12-11 - 9:10 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A truck had driven over an above ground ploy line causing damage to the line releasing 100 bbl of produced water onto the road with 0 bbl recovered. Devon lease operator arrived on location to shut off all transfer pumps going into that line and isolated the leak. Soil samples will be gathered as per the request from the BLM representative.

Describe Area Affected and Cleanup Action Taken.*

Shut off all transfer pumps going into that line & isolated the leak.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mykol Horner</i>	OIL CONSERVATION DIVISION	
Printed Name: Mykol Horner	Approved by District Supervisor Signed By <i>Mike Benavidez</i>	
Title: Field Tech 1	Approval Date: <i>6/16/2011</i>	Expiration Date:
E-mail Address: mykol.horner@dvn.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: Phone: 575-748-0160	<i>7/16/2011</i>	

* Attach Additional Sheets If Necessary

*No Notification Given to OCD
C-141 20 DAYS LATE*

2RP-798