

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

nmlb 11188 37272

**OPERATOR**

Initial Report  Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 104 S. 4 <sup>TH</sup> Street	Telephone No. 575-748-1471	
Facility Name Banjo BNO Federal #1	API Number 30-015-36923	Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NM-102034
--------------------------	--------------------------	------------------------


**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	5	26S	30E	510'	South	330'	West	Eddy

Latitude 32.06576 Longitude 103.89553

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 130 B/PW	Volume Recovered 130 B/PW
Source of Release Discharge hose on water pump	Date and Hour of Occurrence 6/23/2011; AM	Date and Hour of Discovery 6/23/2011; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 6/23/2011, PM (voicemail); 6/23/2011, PM (email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	



If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
A discharge hose on the water pump blew. The pump was turned off and a vacuum truck and roustabout crew were called to the location.

Describe Area Affected and Cleanup Action Taken.\*  
An approximate area of 210' X 27' (all released water was contained in lined/bermed battery). The discharge hose on water pump was repaired, and all produced water was recovered. **Depth to Ground Water: >100' (approximately 173', Section 5, T26S-R30E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on battery being lined/bermed and all water recovered, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Cannon</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amber Cannon	Approved by District Supervisor Signed By <i>Mike Bratcher</i>	
Title: Environmental Regulatory Agent Trainee	Approval Date: <i>7/7/2011</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>acannon@yatespetroleum.com</i>	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: Thursday, June 30, 2011 Phone: 575-748-4111	2RP-802	<i>Final</i>

\* Attach Additional Sheets If Necessary

2RP-802



# New Mexico Office of the State Engineer

## Wells with Well Log Information

(quarters are 1=NW 2=NE 3=SW 4=SE)  
(quarters are smallest to largest) (NAD83 UTM in meters)

POD Number	Sub basin	Use	County	Source	q	q	q	Sec	Tws	Rng	X	Y	Start Date	Finish Date	Log File	Depth Well	Depth Water
<u>C 01360</u>		IND	ED	Shallow	4	3	3	05	26S	30E	602997	3548152	04/26/1952	05/15/1952	11/17/1953	770	173
<u>C 01360</u>	C	PRO	ED	Shallow	4	3	3	05	26S	30E	602997	3548152	04/26/1952	05/15/1952	11/17/1953	770	173
<u>C 01361</u>		IND	ED	Shallow	3	4	3	05	26S	30E	603240	3548157	05/16/1952	06/01/1952	11/17/1953	775	184
<u>C 02165</u>	C	PRO	ED	Shallow				24	26S	30E	610036	3544121*	05/02/1988	05/02/1988	05/05/1988	440	180

**Record Count: 4**

**PLSS Search:**

Township: 26S      Range: 30E

\*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

## Bratcher, Mike, EMNRD

---

**From:** Bob Asher [BobA@yatespetroleum.com]  
**Sent:** Thursday, June 23, 2011 1:54 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Lisa Norton; Jerry Fanning; Amanda Trujillo; Amber Cannon  
**Subject:** Release (Banjo BNO Federal #1)

Mike,

Yates Petroleum Corporation is reporting a release at the following location.

Banjo BNO Federal #1  
30-015-36923  
Section 5, T26S-R30E  
Eddy County, New Mexico

Date/Time of Release: 6/23/2011; AM

Released: 80 B/PW  
Recovered: 80 B/PW  
Battery is lined.

A C-141 Initial Report will be submitted with complete details.

**Robert Asher**  
**Senior Environmental Regulatory Agent**  
**Yates Petroleum Corporation**  
**Office: (575) 748-4217**  
**Cell: (575) 365-4021**  
**Fax: (575) 748-4662**  
**boba@yatespetroleum.com**

Thank you.