


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1270 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action  
OPERATOR

Initial Report  Final Report

*NMLB 11222 50190*

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 101 S. 4 <sup>th</sup> Street	Facility Name Dagger Draw Gas Gathering System (Hinkle Line)	Telephone No. 575-748-1471
Facility Name Dagger Draw Gas Gathering System (Hinkle Line)	API Number	Facility Type Pipeline
Surface Owner Fee	Mineral Owner Fee	Order Number 2RP- 823
Lease No.		

*NB DUP 115 (30-015-28033) FOR DATA ENTRY*

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	28	19S	25E	990	North	600	East	Eddy

NATURE OF RELEASE

Type of Release Gas	Volume of Release 500 MCF Gas	Volume Recovered 0
Source of Release Weld on 8" poly gas line broke	Date and Hour of Occurrence 06/01/2011	Date and Hour of Discovery 06/01/2011- PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOC D/Artesia	
By Whom? Amanda Trujillo - Yates Petroleum Corporation	Date and Hour 06/01/2011 pm called OCD Office. Email followed on 06/02/2011	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.\*

A weld broke on and 8" poly line, causing a gas leak. Valves were shut off to stop leak and make necessary repairs. Leak occurred within in valve box.

Describe Area Affected and Cleanup Action Taken.\*

Leak occurred within a valve box. The impacted area is located around and within the valve box. Vertical and horizontal delineation samples will be taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Depth to Ground Water: >100' (approx. 150', per New Mexico Chevron/Texaco Trend Map); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 20.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By:	
Title: Environmental Scientist	Approved by District Supervisor:	
E-mail Address: atrujillo@yatespetroleum.com	Approval Date: AUG 10 2011	Expiration Date:
Date: Friday, June 17, 2011 Phone: 575-748-4310	Conditions of Approval:	Attached <input type="checkbox"/>

Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

9/10/2011

*2RP-823*

## Bratcher, Mike, EMNRD

---

**From:** Amanda Trujillo [atrujillo@yatespetroleum.com]  
**Sent:** Friday, June 17, 2011 5:46 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Amanda Trujillo  
**Subject:** RE: (Release) Dagger Draw Gas System  
**Attachments:** DDGGS(Hinkle Line) Initial 6-1-11.pdf

C-141 Attached

**Amanda N. Trujillo**  
Environmental Scientist  
Yates Petroleum Corporation  
Office 575-748-4310  
Cell 575-703-6537  
Email [atrujillo@yatespetroleum.com](mailto:atrujillo@yatespetroleum.com)

-----Original Message-----

**From:** Amanda Trujillo  
**Sent:** Friday, June 03, 2011 4:26 PM  
**To:** 'Mike Bratcher (Mike.Bratcher@state.nm.us)'; Jerry Fanning; Bob Asher  
**Subject:** RE: (Release) Dagger Draw Gas System

Mike,

The line was pinched off and capped this morning. A report will follow.

**Amanda N. Trujillo**  
Environmental Scientist  
Yates Petroleum Corporation  
Office 575-748-4310  
Cell 575-703-6537  
Email [atrujillo@yatespetroleum.com](mailto:atrujillo@yatespetroleum.com)

-----Original Message-----

**From:** Amanda Trujillo  
**Sent:** Thursday, June 02, 2011 3:59 PM  
**To:** Mike Bratcher (Mike.Bratcher@state.nm.us); Jerry Fanning; Bob Asher  
**Subject:** (Release) Dagger Draw Gas System

Mr. Mike Bratcher:

Yates Petroleum reports a release at the following location:

Gas line in a valve box near the NDDUP 115 (plugged)  
Sec. 28, Township 19 South, Range 25 East  
Eddy County  
Date of Release: 06/02/11  
Greater than 500 mcf was released  
Cause of release has been isolated and repairs are in progress to stop the release

If you should have any questions please feel free to contact me at the number below.

**Amanda N. Trujillo**  
Environmental Scientist  
Yates Petroleum Corporation  
Office 575-748-4310  
Cell 575-703-6537  
Email [atrujillo@yatespetroleum.com](mailto:atrujillo@yatespetroleum.com)

## **Bratcher, Mike, EMNRD**

---

**From:** Amanda Trujillo [atrujillo@yatespetroleum.com]  
**Sent:** Thursday, June 02, 2011 3:59 PM  
**To:** Bratcher, Mike, EMNRD; Jerry Fanning; Bob Asher  
**Subject:** (Release) Dagger Draw Gas System

Mr. Mike Bratcher:

Yates Petroleum reports a release at the following location:

Gas line in a valve box near the NDDUP 115 (plugged)  
Sec. 28, Township 19 South, Range 25 East  
Eddy County  
Date of Release: 06/02/11  
Greater than 500 mcf was released  
Cause of release has been isolated and repairs are in progress to stop the release

If you should have any questions please feel free to contact me at the number below.

**Amanda N. Trujillo**  
Environmental Scientist  
Yates Petroleum Corporation  
Office 575-748-4310  
Cell 575-703-6537  
Email [atrujillo@yatespetroleum.com](mailto:atrujillo@yatespetroleum.com)

## Bratcher, Mike, EMNRD

---

**From:** Gray, Darold, EMNRD  
**Sent:** Friday, June 03, 2011 7:36 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** reported release

Release reported on 200 line.

Call time: 4:15 p.m. Date: 6/2/2011 Reported by: Amanda Trujillo Ph. #: 575.748.4310

Called to report a gas release on the Dagger Draw gas line in valve box near the NDDUP #115, which is a plugged well. Sec 28 T19S R25E. Problem has been isolated and repairs in progress. More than 500 mcf was released. Please call Amanda Trujillo if you have any more questions.

*Darold Gray*

*NM OCD - Artesia*

*Field Supervisor* ♣

Cell: (575) 626-0843

Off:(575) 748-1283 ext. 113

Fax:(575)748-9720

[darold.gray@state.nm.us](mailto:darold.gray@state.nm.us)

