


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1200 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources



Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NMLB1122253079

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 104 S 4 th Street	Facility Name Dayton ER	Telephone No. 575-748-1471
Facility Name Dayton ER	API Number 30-015-21629	Facility Type battery
Surface Owner Fee	Mineral Owner fee	Order Number 2RP-824
Lease No.		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	21	18S	26E	2310	SOUTH	990	EAST	EDDY

NATURE OF RELEASE

Type of Release WATER	Volume of Release 70	Volume Recovered 60
Source of Release Valve broke	Date and Hour of Occurrence 06/03/2011	Date and Hour of Discovery 06/03/2011- PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD/Artesia	
By Whom? Bob Asher - Yates Petroleum Corporation	Date and Hour 06/03/2011 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*

While working on a 2" valve, the valve broke. The others valves were closed to mitigate the damage but several valves did not hold. After getting valves to hold a vacuum truck was called to pick up standing fluid.

Describe Area Affected and Cleanup Action Taken.*

An approximate size of 03' x 30' was impacted. The impacted area is located near the water tank. Vertical and horizontal delineation samples will taken and analysis ran for TPH and BTEX once all contaminated material has been removed. **Depth to Ground Water: >100'** (approx. 134', per New Mexico State Engineers Office); **Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 20.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By:	
Title: Environmental Scientist	Approved by District Supervisor:	
E-mail Address: atrujillo@yatespetroleum.com	Approval Date: AUG 10 2011	Expiration Date:
Date: Friday, June 17, 2011 Phone: 575-748-4310	Conditions of Approval:	Attached <input type="checkbox"/>

Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**
9/10/2011

2RP-824

Bratcher, Mike, EMNRD

From: Amanda Trujillo [atrujillo@yatespetroleum.com]
Sent: Friday, June 17, 2011 5:48 PM
To: Amanda Trujillo; Bratcher, Mike, EMNRD
Subject: RE: (Release) Dayton ER
Attachments: Dayton ER (Initial 6-3-11).pdf

Attached C-141

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com

-----Original Message-----

From: Amanda Trujillo
Sent: Friday, June 03, 2011 4:11 PM
To: Mike Bratcher (Mike.Bratcher@state.nm.us); Jerry Fanning; Bob Asher
Subject: (Release) Dayton ER

Mr. Mike Bratcher:

Yates Petroleum reports a release at the following location:

Dayton ER
Sec. 21, Township 18 South, Range 26 East
Eddy County
Date of Release: 06/03/11
Approximately 70 barrels of water/condensate were released from a gas line
Approximately 60 barrels were recovered
Cause of release has been isolated and repairs are in progress
Site will be evaluated and a work plan for remediation will be submitted for consideration

If you should have any questions please feel free to contact me at the number below.

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com

Bratcher, Mike, EMNRD

From: Amanda Trujillo [atrujillo@yatespetroleum.com]
Sent: Friday, June 03, 2011 4:11 PM
To: Bratcher, Mike, EMNRD; Jerry Fanning; Bob Asher
Subject: (Release) Dayton ER

Mr. Mike Bratcher:

Yates Petroleum reports a release at the following location:

Dayton ER
Sec. 21, Township 18 South, Range 26 East
Eddy County
Date of Release: 06/03/11
Approximately 70 barrels of water/condensate were released from a gas line
Approximately 60 barrels were recovered
Cause of release has been isolated and repairs are in progress
Site will be evaluated and a work plan for remediation will be submitted for consideration

If you should have any questions please feel free to contact me at the number below.

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com