

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | | | |
|-----------------|--|---------------|----------------|
| Name of Company | Plains Pipeline LP | Contact | Camille Bryant |
| Address | 2530 State Hwy. 214, Denver City, TX 79323 | Telephone No. | (575) 441-1099 |
| Facility Name | Jal Tank Farm Tank Booster 1287 | Facility Type | Pump |

| | | | | | |
|---------------|---------------------|---------------|--|-----------|--|
| Surface Owner | Plains Pipeline, LP | Mineral Owner | | Lease No. | |
|---------------|---------------------|---------------|--|-----------|--|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| P | 32 | 25S | 37E | | | | | Lea |

Latitude N 32.08076° Longitude W 103.17807°

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|-----------------------------|--|----------------------------|--------------------|
| Type of Release | Crude Oil | Volume of Release | 10 bbls | Volume Recovered | 0 bbls |
| Source of Release | Pump | Date and Hour of Occurrence | 02/21/2015 @ 10:30 | Date and Hour of Discovery | 02/21/2015 @ 10:30 |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | | If YES, To Whom? Verbal notification to Bill Sonnamaker (voicemail) | | |
| By Whom? | Camille Bryant | | Date and Hour 02/21/2015 @ 13:00 | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | If YES, Volume Impacting the Watercourse. | | |



RECEIVED
By OCD; Dr. Oberding at 9:46 am, Mar 11, 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The pump driver on (electric motor) bearings failed which transferred misalignment, heat, and vibration to the pump and mechanical seal assembly and caused subsequent seal failure. Failure of the mechanical seal allowed crude oil to escape and ignite. The release was confined inside the firewall at the facility. The fire was extinguished and the seal, motor and pipe was replaced.

Describe Area Affected and Cleanup Action Taken. The released crude oil was contained inside the firewall of the facility. The impacted area will be remediated as per applicable NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|--|---|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Camille Bryant | Approved by District Supervisor |  |
| Title: Remediation Coordinator | Approval Date: 03/11/2015 | Expiration Date: 06/11/2015 |
| E-mail Address: cjbryant@paalp.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 3/10/15 Phone: (575) 441-1099 | Site samples required. Delineate and remediate area as per NMOCD guides. | IRP-3570 34053 |

* Attach Additional Sheets If Necessary

nTO1508239951

fTO1508239710

pTO1508240264