

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
JUN 21 2011  
NMOCD ARTESIA

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

nmls1122348831

**OPERATOR**  Initial Report  Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Y Energy State	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-36033
---------------	-------	---------------	-------------------------------


**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	32	18S	30E					Eddy

Latitude 32 42.164 Longitude 103 59.980

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	15bbls	Volume Recovered	13bbls
Source of Release	Water tank load line	Date and Hour of Occurrence	06/07/2011	Date and Hour of Discovery	06/07/2011 8:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A hole developed in the load line causing produced water to be released inside the dike walls of the facility. The load line has been replaced.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 15bbls of produced water was released from the load line and we were able to recover 13bbls with a vacuum truck. All fluid was contained inside the berm walls of the facility. All standing fluid has been removed and contaminated soil and gravel has been removed and hauled to disposal. Tetra Tech will sample the spill site are to delineate an possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Josh Russo	Signed By:	
Title:	HSE Coordinator	Approved by District Supervisor:	
E-mail Address:	jrusso@conchoresources.com	Approval Date:	AUG 11 2011
Date:	06/21/2011	Expiration Date:	
Phone:	432-212-2399	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**  
9/11/2011

JRP-831

**Bratcher, Mike, EMNRD**

---

**From:** Joshua Russo [jrusso@conchoresources.com]  
**Sent:** Tuesday, June 21, 2011 4:00 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Tavarez, Ike; Dorey, Kim; tom.k.franklin@tetrattech.com  
**Subject:** C-141 - Y Energy State TB  
**Attachments:** Y ENERGY STATE TANK BATTERY -- DATE OF RELEASE -- 06-07-2011.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release at the Y Energy State Tank Battery.

Thanks,

**Joshua Russo**

HSE Coordinator  
550 W. Texas Ave, Suite 100  
Midland, Texas 79701  
Phone: (432) 683-7443  
Cell: (432) 212-2399  
[jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)



**CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.**