

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nmlb1122742820*

**OPERATOR**

Initial Report  Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>TH</sup> Street		Telephone No. 575-748-1471
Facility Name Rudolph ATX State Com. #3-H	API Number 30-015-37997	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. V-4567
------------------------	------------------------	---------------------


**LOCATION OF RELEASE**

Unit Letter M	Section 16	Township 19S	Range 31E	Feet from the 330'	North/South Line South	Feet from the 660'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.65389 Longitude 103.88026

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 75 B/PW	Volume Recovered 75 B/PW
Source of Release Water tank	Date and Hour of Occurrence 7/21/2011; AM	Date and Hour of Discovery 7/21/2011; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 7/21/2011, AM (email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.\*  
Water hauler did not pick up load of water before it overflowed out of tank.. The well was shut in, vacuum truck was called to the location.

Describe Area Affected and Cleanup Action Taken.\*  
An approximate area of 100' X 5' (all released water was contained in lined/bermed battery). All produced water was recovered. **Depth to Ground Water: >100' (approximately 130', Section 36, T19S-R31E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on battery being lined/bermed and all water recovered, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher	Signed By <u><i>Mike Bratcher</i></u> Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date: <b>AUG 15 2011</b>	Expiration Date: <b>NA</b>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <b>NA</b> <i>Final</i>	Attached <input type="checkbox"/>
Date: Friday, July 22, 2011 Phone: 575-748-4217	2RP- <b>847</b>	

\* Attach Additional Sheets If Necessary

*2RP-847*



# New Mexico Office of the State Engineer

## Wells with Well Log Information

(quarters are 1=NW 2=NE 3=SW 4=SE)  
(quarters are smallest to largest) (NAD83 UTM in meters) (in feet)

POD Number	Sub-basin	Use	County	Source	q	q	q	Sec	Tws	Rng	X	Y	Start Date	Finish Date	Log File Date	Depth Well	Depth Water
CP 00641 EXPL	EXP	ED		6416 4	4	1	36	19S	31E		610247	3609634*	02/11/1982	02/12/1982	02/23/1982	300	130
CP 00642 EXPL	EXP	ED			2	2	25	19S	31E		611025	3611657*	02/10/1982	02/01/1982	02/23/1982	250	

**Record Count: 2**

**PLSS Search:**

Township: 19S      Range: 31E

\*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

**Bratcher, Mike, EMNRD**

---

**From:** Bob Asher [BobA@yatespetroleum.com]  
**Sent:** Thursday, July 21, 2011 8:18 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Lisa Norton; Amanda Trujillo; Amber Cannon; Jeremy Haass; Jerry Fanning  
**Subject:** Release (Rudolph ATX State Com. #3-H)

Mike,

Yates Petroleum Corporation is reporting a release at the following location.

Rudolph ATX State Com. #3-H  
30-015-37997  
Section 16, T19S-R31E  
Eddy County, New Mexico

Date/Time of Release: 7/21/2011; PM

Released: Approximately 50-75 B/PW  
Recovered: 50-75 B/PW (Battery is bermed and lined).

A C-141 Initial/Final Report will be submitted with complete details.

If you have any questions, please contact me.

Thank you.

**Robert Asher**

**Senior Environmental Regulatory Agent**  
**Yates Petroleum Corporation**  
575-748-4217 (Direct)  
575-365-4021 (Cell)  
[boba@yatespetroleum.com](mailto:boba@yatespetroleum.com)