

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 1, 2011

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*NMLB1122948592*

**OPERATOR**

Initial Report  Final Report

Name of Company	Apache Corporation	873	Contact	Natalie Gladden
Address	PO Box 1849, Eunice NM 88231		Telephone No.	575-390-4186
Facility Name	Empire Abo Unit M-14		Facility Type	Production Well

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	30-015-22834
---------------	-----	---------------	-----	-----------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	11	18S	27E	228	FNL	2280	West	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced water and hydrocarbon	Volume of Release	<del>100</del> 1.50	Volume Recovered	100
Source of Release	Fiberglass line	Date and Hour of Occurrence	04/29/11	Date and Hour of Discovery	Same
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Natalie Gladden	Date and Hour	04/29/11 12pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

**RECEIVED**  
AUG 11 2011  
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The buried emulsion line busted, ran across the M14 location down lease road on of the historical BP site at the L14. Therefore both sites were affected. Trucks recovered standing fluid.

Describe Area Affected and Cleanup Action Taken.\*  
Both sites will be remediated to meet NMOCD/BLM standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Natalie Gladden</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Natalie Gladden	Signed By:	<i>Mike Bratcher</i>
Title:	EHS Environmental Tech	Approved by District Supervisor:	
E-mail Address:	natalie.gladden@apachecorp.com	Approval Date:	AUG 17 2011
Date:	05/02/2011	Expiration Date:	
Phone:	575-390-4186	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**  
9/17/2011

*2LP-860*