

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nmlb1122954397 OPERATOR Initial Report Final Report

Name of Company Apache Corporation <i>873</i>	Contact Natalie Gladden
Address PO Box 1849, Eunice NM 88240	Telephone No. 575-390-4186
Facility Name Red Fed Water Station (near Red Fed #2)	Facility Type Water Station
Surface Owner BLM	Mineral Owner State
API No. 30-015-30143	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	17	17S	30E	1650	FSL	2310	FEL	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release >150	Volume Recovered 150
Source of Release Truck drivers fell asleep	Date and Hour of Occurrence 04/09/11	Date and Hour of Discovery 04/09/11
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Natalie Gladden	Date and Hour 04/11/11 304pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

RECEIVED
AUG 11 2011
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
COG's line went down and therefore we were trucking the water, two trucks were hauling 24hrs a day and both went to sleep, which caused the tanks on the trucks to overflow; releasing an unknown volume. We recovered 150bbbls.

Describe Area Affected and Cleanup Action Taken.*
Inside of the bermed area will be hand dug and the location pad will be excavated to meet NMOCD/BLM Standards for Remediation.

No Groundwater

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist	
Title: EHS Environmental Tech	Approval Date: AUG 17 2011	Expiration Date:
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 04/11/11 Phone: 575-390-4186	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

9/17/2011
2RP-861

* Attach Additional Sheets If Necessary