

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-37845

Release Notification and Corrective Action

nmlb 1123836874 258462 OPERATOR  Initial Report  Final Report

Name of Company	NADEL AND GUSSMAN HEYCO, LLC	Contact	Keith Cannon or Tammy R. Link
Address	PO Box 1936, Roswell 88202-1936	Telephone No.	(575) 623-6601
Facility Name	Aid State #6	Facility Type	

Surface Owner	USA	Mineral Owner	State of New Mexico	Lease No.	K-3630-2
---------------	-----	---------------	---------------------	-----------	----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	13	17S	28E	2310'	N	330'	E	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	130 bbls of Water	Volume of Release	130 bbls	Volume Recovered	125 bbls
Source of Release	Lightening struck Fiberglass Water Tank	Date/Hour of Release	8/11/2011	Date/Hour Discovered	8/11/11 4:00 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Randy Dade w/OCD in Artesia <i>NOTICE NOT PROVIDED TO M&amp;S</i>		
By Whom?	Keith Cannon	Date and Hour	5:45 pm 8/11/2011		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Lightening struck Fiberglass Water Tank all fluid was contained by Dykes.  
Fixed problem, remove water tank from Dykes.

Describe Area Affected and Cleanup Action Taken.\*

Removing contaminated gravel with liner, rebuilding Dyke and reline & set tanks.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tammy Link</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tammy Link	Signed By <i>M. L. Brandon</i>	
Title: Engineering Tech	Approved by District Supervisor:	
E-mail Address: tlink@heycoenergy.com	Approval Date: <b>AUG 26 2011</b>	Expiration Date:
Date: 8/11/11 Phone: (505)623-6601	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**  
9/26/2011

*2 RP-866*

