

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nmls1004242112

Name of Company Devon Energy <i>6137</i>		Contact Jerry Mathews	
Address 6488 Seven Rivers Hwy - P.O. Box 250		Telephone No. (575) 748-5234 (cell)	
Facility Name Joell 6 #2 Tank Battery		Facility Type Tank Battery	
Surface Owner: State	Mineral Owner: State	API # 30-015-33292	

OPERATOR Initial Report Final Report

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	6	23S	27E	1530	North	1130	East	Eddy

Latitude N 32° 20.210' Longitude W 104° 13.484'

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 33 bbl	Volume Recovered 0 bbl fluids
Source of Release Water Tank	Date and Hour of Occurrence 1/16/10 10:00 AM	Date and Hour of Discovery 1/16/10 1:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Artesia Office, NMOCD and BLM	
By Whom? Shannon Moss - Foreman	Date and Hour 1/16/10 3:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Circulating valve on the back of the water tank had frozen and ruptured.

Describe Area Affected and Cleanup Action Taken.*

Visibly impacted soil was removed from an area measuring approximately 45' x 110' and disposed at an NMOCD approved facility. Soil samples were collected from the excavation until all TPH and chloride concentrations were reported below the NMOCD remediation standards. Excavated soil was disposed at an NMOCD approved disposal facility. Figures are attached that show the site location, the tank battery and sample point locations (Fig #1 through Fig #3). Laboratory data and chain of custody documentation is also attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jerry Mathews</i>	OIL CONSERVATION DIVISION	
Printed Name: Jerry Mathews	Signed By <i>Mike Brannon</i>	
Title: Workover / Completion Foreman	Approved by District Supervisor:	
E-mail Address: Jerry.Mathews@dvn.com	Approval Date: SEP 20 2011	Expiration Date: NA
Date: 6/17/10 Phone: (575) 748-5234	Conditions of Approval: <i>NA</i>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-386