

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 1, 2011

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-38142

**Release Notification and Corrective Action**

258462

**OPERATOR**

Initial Report  Final Report

Name of Company; Nadel and Gussman HEYCO, LLC	Contact; Keith Cannon
Address; P.O Box 1936, Roswell N.M 88202	Telephone No. 575-626-1936
Facility Name; AID STATE #8	Facility Type; Oil Tank Battery

Surface Owner; State	Mineral Owner; State	Lease No. K-3630-2
----------------------	----------------------	--------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	13	17S	28E	990	North	330	East	Eddy

Latitude 32.840325° N Longitude 104.121932° W

**NATURE OF RELEASE**

Type of Release;	Volume of Release l bbl	Volume Recovered, N/A
Source of Release	Date and Hour of Occurrence 7/29/2011, 7:30pm	Date and Hour of Discovery 7/29/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken\*

Lighting hitting fiberglass water tank. Burnt tank, No oil tanks effected. Tank was empty prior to fire

Describe Area Affected and Cleanup Action Taken.\*

Removed oil tanks and flow lines out from dyke. Pick up and removed old tank liner and fiberglass water tank hauled to CRI. Reline dyke with 20 mil liner, sand blasted oil tank and repainted. Rebuild tank battery. Put well back on production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature: <i>Keith Cannon</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Keith Cannon	Signed By <i>Mike Brandon</i> Approved by District Supervisor	
Title: Drilling Superintendent	Approval Date: SEP 13 2011	Expiration Date: NA
E-mail Address: kcannon@heycoenergy.com	Conditions of Approval: <i>NA Final</i>	Attached <input type="checkbox"/>
Date: 9/7/2011	Phone: 575-623-6601	

\*: Attach Additional Sheets If Necessary

2PP-858