

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-30448

Release Notification and Corrective Action

NMLD1125557019

6137

OPERATOR

Initial Report Final Report

Name of Company: Devon Energy Production Co LP	Contact: Merle Lewis
Address: PO BOX 250, Artesia, NM 88211	Telephone No.: 575-748-0184 or 575-748-6304
Facility Name: Shugart 23 Fed Com #1	Facility Type: Oil well
Surface Owner: State	Mineral Owner: BLM
Lease No.: LC - 065680	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	23	18S	31E	1650	S	1980	E	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 70 bbls	Volume Recovered: 31 bbls
Source of Release: Hole in oil tank	Date and Hour of Occurrence: 9/4/2011 (? Hour)	Date and Hour of Discovery: 9/4/2011, 12:25 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Paul Evans / BLM OCD - 9/6/11 10:25 AM	
By Whom? Merle Lewis, Asst. Foreman	Date and Hour: 9/4/11, 12:50 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
SEP 07 2011
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Hole in oil tank. Immediately, a vacumm truck was used to pick up the spill. 31 bbls were recovered out of 70 bbls.

Describe Area Affected and Cleanup Action Taken.*
60' x 20' in containment area. Our plan includes moving the oil tanks and rebuilding the battery at another part of the location and soil remediation will be completed in the spill area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Merle Lewis</i>	OIL CONSERVATION DIVISION	
Printed Name: Merle Lewis	Signed By: <i>Mike Bennett</i> Approved by District Supervisor:	
Title: Assistant Production Foreman	Approval Date: SEP 12 2011	Expiration Date:
E-mail Address: Merle.Lewis@dvn.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: 9/6/2011 Phone: 575-748-0184	<i>2 RP-896</i>	

* Attach Additional Sheets If Necessary

PROPOSAL NOT LATER THAN:
10/12/2011