

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-29847

**Release Notification and Corrective Action**

nmlb1125754115

**OPERATOR**

Initial Report  Final Report

Name of Company BOPCO, L.P. <b>260737</b>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Poker Lake Unit #139	Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No
-----------------------	-----------------------	----------


**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	24	24S	30E					Eddy

Latitude\_N 32.201670 Longitude W 103.832130

**NATURE OF RELEASE**

Type of Release: Produced water and crude oil	Volume of Release: 25 bbls of produced water and 5 bbls of crude oil.	Volume Recovered: 8 bbls total fluid
Source of Release: Pumping well stuffing box.	Date and Hour of Occurrence: 8/23/11, Hour unknown	Date and Hour of Discovery: 8/23/11 10:20 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency operator ext.104	
By Whom? Tony Savoie	Date and Hour 8/23/11 11:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* A pumping unit stuffing box packing failed, the packing was replaced.

Describe Area Affected and Cleanup Action Taken.\* Approximately 4215 sq. ft. of caliche well pad, all of the free standing fluid was removed with a vacuum truck and the saturated caliche was scraped up and stockpiled on the well pad location. A remediation plan will be developed in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by <u>Signed Supervisor</u>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: <b>SEP 14 2011</b>	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/11/11 Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	

**SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**  
10/14/2011

2RP-901

\* Attach Additional Sheets If Necessary