

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-10048

Release Notification and Corrective Action

NMLB/126430576

OPERATOR

Initial Report Final Report

Name of Company BOPCO, L.P. <u>260737</u>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Continental Federal Battery #1	Facility Type E&P

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No.
-----------------------------------	-----------------------------------	-----------


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	20	25S	30E					Eddy

Latitude N 32.120920 ___ Longitude W 103.907974 ___

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 30 bls crude oil	Volume Recovered: 0
Source of Release: Heater Treater	Date and Hour of Occurrence 8/30/11, Hour unknown	Date and Hour of Discovery 8/30/11 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour <u>8/23/11</u> approximately 1:00 p.m. <u>8/30/11</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The man way cover had internal corrosion. The heater was isolated and crews are working to repair the man way cover.

Describe Area Affected and Cleanup Action Taken.* Approximately 3800 sq. ft of pasture land was affected by the release, all of the product had soaked into the ground, this was in an area that had been impacted by spills in the past. The Site remediation for the produced water and crude oil spill will follow the NMOCD and BLM guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor Signed By <u>Mike Benjamin</u>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: SEP 21 2011	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>10/21/2011</u>	Attached <input type="checkbox"/>
Date: 9/11/11 Phone: 432-556-8730		<u>2RP-904</u>

* Attach Additional Sheets If Necessary