

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
SEP 13 2011
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-32040

Release Notification and Corrective Action

nMLB1126433494 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Antelope State Tank Battery	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	Lease No. B-3627
---------------	-------	---------------	------------------

Antelope 36 St Com #1 Btry

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	36	17S	31E					Eddy

Latitude 32.7881 Longitude 103.8263

NATURE OF RELEASE

Type of Release	Produced fluid	Volume of Release	15bbls	Volume Recovered	13bbls
Source of Release	Water tank	Date and Hour of Occurrence	08/30/2011	Date and Hour of Discovery	08/30/2011 11:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Water hauling company did not keep up with water in tank causing the tank to overflow.

Describe Area Affected and Cleanup Action Taken.*

Initially 15bbls were released from the water tank and we were able to recover 13bbls with a vacuum truck. The spill area measured 6' x 60' in front of the water and oil tanks inside the tank battery. All fluid was contained inside the tank battery walls. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Signed By <i>M. L. Brannon</i> Approved by District Supervisor:	
Title:	HSE Coordinator	Approval Date:	SEP 21 2011
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	09/13/2011	Phone:	432-212-2399

Conditions of Approval:
Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**
10/21/2011

Attached

2RP-906

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Tuesday, September 13, 2011 4:14 PM
To: Bratcher, Mike, EMNRD
Cc: Tavares, Ike; Dorey, Kim; tom.k.franklin@tetrattech.com
Subject: C-141 - Antelope State TB
Attachments: img-913181140-0001.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at the Antelope State Tank Battery.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.