

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nMLB 1128633884

OPERATOR

Initial Report Final Report

Name of Company	Geronimo SWD, LLC 263684	Contact	James B. Campanella
Address	PO Box 568, Artesia, NM 88211	Telephone No.	(575)746-1280
Facility Name	Green A Federal SWD	Facility Type	Saltwater Disposal

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-21748
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	29	17-S	29-E	1980	South	1980	West	Eddy

Latitude 32.8036949749656 Longitude 104.099097557391

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	140 BBLs	Volume Recovered	136 BBLs
Source of Release	Water Tank	Date and Hour of Occurrence	08/23/11 7:00 AM	Date and Hour of Discovery	08/23/11 8:30 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher w/NMOCD Dist 3		
By Whom?	James B. Campanella	Date and Hour	08/23/11 9:00 AM	<i>(No Record of Notification)</i>	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Hole in water tank. Cleaned out tank, sand blasted and welded metal piece over hole. Recoated tank.

Describe Area Affected and Cleanup Action Taken.*

All fluid was contained in lined firewall. Picked up fluid with vacuum truck and pumped into other facility tank.



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>James B. Campanella</i>	OIL CONSERVATION DIVISION	
Printed Name: James B. Campanella	Signed By: <i>Mike Bratcher</i> Approved by Environmental Specialist.	
Title: Member/Manager	Approval Date: OCT 13 2011	Expiration Date: <i>NA</i>
E-mail Address: judahoil@yahoo.com	Conditions of Approval: <i>NA</i>	Attached <input type="checkbox"/>
Date: 9/19/2011	Phone: (575)746-1280	

* Attach Additional Sheets If Necessary

2RP-911