


District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

**30-015-29530 Release Notification and Corrective Action**

NMLB1129434964 OPERATOR  Initial Report  Final Report

Name of Company: LINN Energy <u>269324</u>	Contact: Joe Hernandez
Address: 2130 W Bender Blvd. - Hobbs, NM	Telephone No.: 575-942-8675
Facility Name: Turner B South Well 111 Flow Line	Facility Type: Producing Oil Well

Surface Owner: BLM	Mineral Owner: BLM	Lease No.: LC-029395-B
--------------------	--------------------	------------------------

**LOCATION OF RELEASE**

Unit Letter	Section 30	Township 17S	Range 31E	Feet from the 330	North/South Line S	Feet from the 1825	East/West Line E	County Eddy
-------------	---------------	-----------------	--------------	----------------------	-----------------------	-----------------------	---------------------	----------------

Latitude: 32 48' 8.322" Longitude: 103 54' 35.936"

**NATURE OF RELEASE**

Type of Release: Oil & Produced Water	Volume of Release: 25 bbls	Volume Recovered: 0
Source of Release: Flowline Leak	Date and Hour of Occurrence: 09/28/11 - 0700	Date and Hour of Discovery: 09/28/11 -0800
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? T. Gregston BLM, M. Bratcher, OCD	
By Whom? Fred Holmes	Date and Hour: 0929/11-0730	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Coupling thread integrity failed, back pressure caused line to break. Well was shut in, repairs made of the line.		
Describe Area Affected and Cleanup Action Taken.* : Area impacted is "tear-drop shaped" includes road and portions of the pasture. Pasture area impact is approximately 560' long, the wider portion of the spill area is approximately 50' in diameter and as it flow northward, it reduces to 10-15' wide. Site will have to be delineated prior to development of a corrective action plan. Delineation is pending. Also, note the site is in a known cultural resource area.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jose Hernandez	Signed By <u>Mike Beaman</u> Approved by District Supervisor:	
Title: Foreman	OCT 21 2011	Expiration Date:
E-mail Address: jhernandez@linneenrgy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/14/11 Phone: 575-738-1739		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**  
11/21/2011

2RP-932

**Bratcher, Mike, EMNRD**

---

**From:** Fred Holmes [fred@etechemv.com]  
**Sent:** Friday, October 14, 2011 3:58 PM  
**To:** 'Gregston, Terry G'; Bratcher, Mike, EMNRD  
**Cc:** 'Daniel Frick'; 'Ron Ragland'; 'Joe Hernandez'  
**Subject:** LINN Energy Turner #111 Initial Notification  
**Attachments:** LINN Turner B South 111 FL Release \_ Initial C-141\_101411.pdf

Terry & Mike:

Please find attached the initial notification for the above referenced site. Assessment and corrective action plan are pending.

Respectfully:

*Fred Holmes*

**Etech Environmental & Safety Solutions, Inc.**

P.O. Box 8469  
Midland, Texas 79708-8469  
Phone: 432-563-2200  
Fax: 432-563-2213  
E-mail: [fred@etechemv.com](mailto:fred@etechemv.com)

**CONFIDENTIAL**

*This e-mail message, including any attachments, is intended solely for the individual(s) named above. It contains confidential and/or proprietary information. If you are not the intended recipient, please do not read, copy or distribute it or any information it contains. Please immediately notify the sender by return mail and delete it.*