

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-31647

Release Notification and Corrective Action

nMLB1129454400

OPERATOR

Initial Report Final Report

Name of Company-Cimarex Energy	162683	Contact- James Tinney
Address-600 N Marienfeld Ste 600, Midland Tx 79701		Telephone No. 575 706 0095
Facility Name-west shugart 31 fed 1		Facility Type- Tank battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County - Eddy
-------------	---------	----------	-------	---------------	------------------	---------------	----------------	---------------

Latitude-32-42'-33.4" N 32.7093 Longitude-103-54'-57.1" W 103.9159


NATURE OF RELEASE

Type of Release- crude oil - produced water	Volume of Release- 5 oil and 10 water	Volume Recovered- 5 oil and 10 water
---	---------------------------------------	--------------------------------------

Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?
--	------------------

Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.
---	---

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Take. Unauthorized unload into production water tank (260 bbls Approx) was unloaded to water tank causing water tank to spill over to overflow tank causing overflow tank to spill on to ground, all fluid was contained in side lined berm. Had vac truck pick up standing oil and water

Describe Area Affected and Cleanup Action Take area inside lined berm was all that was affected, vac truck picked up stand fluid and put into water tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: James Tinney	Approved by District Supervisor:-	Accepted for record NMOCD OCT 21 2011
Title: Assistant Production Foreman	Approval Date:	Expiration Date:
E-mail Address: jtinney@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-5-11 Phone: 575-706-0095		2728-936

* Attach Additional Sheets If Necessary

- Form is incomplete
- Form has been modified
- Form is not current version