


District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit to the appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nMLB1131129093 OPERATOR Initial Report Final Report

Name of Company Linn Operating <u>269324</u>	Contact Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No 575-738-1739
Facility Name: Skelly Unit # 199	Facility Type: Single Tank Battery
Surface Owner: BLM	Mineral Owner: BLM
API No : 3001528972	

LOCATION OF RELEASE

Unit Letter N	Section 15	Township 17S	Range 31E	Feet from the 1310	North/South Line FSL	Feet from the 2546	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32° 49' 51 0" Longitude: -103° 51' 28.4"

NATURE OF RELEASE

Type of Release <u>Land PW</u>	Volume of Release 1	Volume Recovered 0.5
Source of Release <u>Produced Water ?</u>	Date and Hour of Occurrence 10/28/2011 9 00am	Date and Hour of Discovery 10/28/2011 9 30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully *		
Describe Cause of Problem and Remedial Action Taken * Back pressure valve had trash in it		
Describe Area Affected and Cleanup Action Taken * Pick up fluid, disposed by Gandy Service		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature	OIL CONSERVATION DIVISION	
Printed Name Joe Hernandez	Signed By <u>M. L. Brannon</u> Approved by District Supervisor.	
Title Production Foreman	Approval Date NOV 07 2011	Expiration Date
E-mail Address jhernandez@linenergy.com	Conditions of Approval	Attached <input type="checkbox"/>
Date 11-02-2011 Phone 575-942-9492	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:
12/7/2011

2 RP - 947

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Wednesday, November 02, 2011 9:55 AM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick
Subject: Linn- Skelly # 199- Initial C141
Attachments: Skelly # 199 Initial C141 11-02-11.pdf

Please find attached the C141 for the above referenced location.

Thank you,

Theresa McCracken

LINN Operating
2130 W. Bender Blvd
Hobbs, NM 88240
(575)738-1739
tmccracken@linnenergy.com