

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

OCT 28 2011

RECEIVED

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>ConocoPhillips Company</b>	Contact <b>John W. Gates</b>
Address <b>3300 North A St. Bldg 6, Midland, TX 79705-5406</b>	Telephone No. <b>505.391.3158</b>
Facility Name <b>MCA</b>	Facility Type <b>Oil and Gas</b>

Surface Owner <b>Federal</b>	Mineral Owner <b>Federal</b>	Lease No <b>029405B</b>
------------------------------	------------------------------	-------------------------

**LOCATION OF RELEASE** *NEARBY WELL MCA #265 - 30-025-23686*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>L</b>	<b>20</b>	<b>17S</b>	<b>32E</b>		<b>100' North of MCA 265</b>			<b>Lea</b>

Latitude Longitude

**NATURE OF RELEASE**

Type of Release <b>Crude Oil &amp; Produced Water</b>	Volume of Release <b>14bbl (8oil, 6water)</b>	Volume Recovered <b>(0oil, 0water)</b>
Source of Release <b>Hole in a 2 7/8" steel test line</b>	Date and Hour of Occurrence <b>10/25/11 1200</b>	Date and Hour of Discovery <b>10/25/11 1600</b>

Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?
--	------------------

By Whom?	Date and Hour
----------	---------------

Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.
---	---

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
**Hole in a 2 7/8" steel test line due to age/fatigue. Vacuum truck was called but no trucks were available to respond to pick up standing fluids**

Describe Area Affected and Cleanup Action Taken.\*  
**Area affected is a 25' X 60' X 10" area of pasture land. ConocoPhillips MSO installed emergency repair clamp until permanent repairs can be made.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>John W. Gates</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>John W. Gates</b>	ENV ENGINEER: Approved by District Supervisor: <i>Steph Labadie</i>	
Title: <b>HSER Lead</b>	Approval Date: <b>11/09/11</b>	Expiration Date: <b>01/09/12</b>
E-mail Address: <b>John.W.Gates@conocophillips.com</b>	Conditions of Approval: <b>DELINEATE HUR &amp; VERT EXTENT OF CONTAMINATION. SUBMIT FINAL C-141</b>	
Date: <b>10/28/11</b> Phone: <b>505.391.3158</b>	Attached <input type="checkbox"/> <b>IR-11-11-2756</b> <b>BY 01/09/12.</b>	

• Attach Additional Sheets If Necessary

NOV 15 2011