

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nMLB1034031929* OPERATOR  Initial Report  Final Report

Name of Company <b>COG Operating LLC</b>	Contact <b>Pat Ellis</b>	
Address <b>550 W. Texas, Suite 1300 Midland, Texas 79701</b>	Telephone No. <b>(432) 685-4332</b>	
Facility Name <b>Ruthie Fee #1</b>	Facility Type <b>Tank Battery</b>	
Surface Owner: Private	Mineral Owner	Lease No. <b>API 30-015-33403</b>


**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	10	22S	27E					Eddy

Latitude N 32 24.170° Longitude W 103 11.024°

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release 17 bbls	Volume Recovered 15 bbls
Source of Release: Circulating pump discharge valve	Date and Hour of Occurrence 11/22/10	Date and Hour of Discovery 11/22/10 11:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A cow got inside the tank battery and rubbed the circulating pump discharge valve partially open. The valve has been closed.		
Describe Area Affected and Cleanup Action Taken.* Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ike Tavarez <i>Report In COG</i>	Approved by <i>Mike Brannon</i> Signed By District Supervisor	
Title: Project Manager	Approval Date: <b>NOV 18 2011</b>	Expiration Date: <i>N/A</i>
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: <i>6-20-11</i> Phone: (432) 682-4559		



\* Attach Additional Sheets If Necessary

*JRP-490*