

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*NMLB 10259 41828*

<b>OPERATOR</b>		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company <b>COG Operating LLC</b>	Contact <b>Pat Ellis</b>		
Address <b>550 W. Texas, Suite 1300 Midland, Texas 79701</b>	Telephone No. <b>(432) 230-0077</b>		
Facility Name <b>GJ West COOP #135</b>	Facility Type <b>Flow line</b>		
Surface Owner <b>State</b>	Mineral Owner	Lease No. <b>30-015-28591</b>	


**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	22	17S	29E	990	North	2310	East	Eddy

Latitude N **32.82596°**

Longitude **103.83884°**

**NATURE OF RELEASE**

Type of Release <b>Produced fluids</b>	Volume of Release <b>15 bbls</b>	Volume Recovered <b>12 bbls</b>
Source of Release <b>Flow line</b>	Date and Hour of Occurrence <b>1/19/2010</b>	Date and Hour of Discovery <b>1/19/2010 8:00 am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher - OCD</b>	
By Whom? <b>Gail Lamb</b>	Date and Hour <b>1/19/2010</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	
If a Watercourse was Impacted, Describe Fully.* <b>N/A</b>		
Describe Cause of Problem and Remedial Action Taken.* <b>A flow line ruptured and leaked releasing produced fluids into the pasture. The ruptured flow line was replaced with a new flow line.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>Tetra Tech inspected the site and collected soil samples to define spills extents. Once defined, a work plan was submitted to the NMOCD for approval. As approved, the impacted soils were removed to the appropriate depths and hauled to proper disposal. The excavation was backfilled with clean soil to grade. Tetra Tech prepared closure report and submitted to NMOCD for review.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Ike Tavarez (agent for COG)</b>	Signed By <u><i>Mike Bratcher</i></u> Approved by District Supervisor	
Title: <b>Project Manager</b>	Approval Date: <b>NOV 18 2011</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>ike.tavarez@tetrattech.com</b>	Conditions of Approval: <u><i>N/A Final</i></u>	Attached <input type="checkbox"/>
Date: <b>6-13-11</b> Phone: <b>(432) 686-3023</b>		

**RECEIVED**  
JUL 05 2011  
NMOCD ARTESIA

\* Attach Additional Sheets If Necessary

*2RP-434*