

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NM/CB/1108929104 OPERATOR Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Mimosa Federal SWD #3Y	API Number 30-015-32896	Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NM-39635
--------------------------	--------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter P	Section 4	Township 20S	Range 24E	Feet from the 635	North/South Line South	Feet from the 330	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.59732 Longitude 104.58540

NATURE OF RELEASE

Type of Release Oil	Volume of Release 20 B/O	Volume Recovered 0 B/O
Source of Release Sales Line	Date and Hour of Occurrence 2/20/2011; AM	Date and Hour of Discovery 2/20/2011; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	


RECEIVED
NOV 29 2011
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Sales line collar came apart to cause release. Shut in valves and line was repaired.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 30' X 500' (outside of battery). No oil was recovered. Entire release area has been sprayed with Microblaze. Vertical and horizontal delineation samples have been taken (3/9/2011) and analysis to be run for TPH & BTEX Based on results a work plan will be submitted to address remedial actions to be taken. A series of Microblaze and nitrogen fertilizer applications were made until analytical results were below RRAL's for the site ranking of 10. **Depth to Ground Water: >100' (approximately 268', per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: 200-1000', SITE RANKING IS 10. Based on remedial actions taken and enclosed analytical results, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By  Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date: NOV 30 2011	Expiration Date: NA
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: NA Final	Attached <input type="checkbox"/>
Date: Tuesday, November 29, 2011 Phone: 575-748-4217	2RP-643	

* Attach Additional Sheets If Necessary