

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
NOV 18 2011
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nMLB/133634980 OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Max Friess # 1	Facility Type: Injection well
Surface Owner: BLM	Mineral Owner: BLM
API No.: 3001505459	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	30	17S	31E	660	N	1980	E	Eddy

Latitude: 32° 48' 39.1" Longitude: -103° 54' 24.6"

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 2 / 8	Volume Recovered: 0.5 / 1
Source of Release: Tank	Date and Hour of Occurrence: 11/15/2011 4:54pm	Date and Hour of Discovery: 11/15/2011 5:15pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher- NM OCD / T. Gregston- BLM	
By Whom? Joe Hernandez	Date and Hour 11/16/2011 10:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Tied 500bbl flow back to well head to flow back for acid job, well flowed at steady for 5hr and well kicked off overflowed tank oil/produced water came out top. Flow direction SW off location, N NW, on location and then off NW location. Contractor drove up to location as tank started to run over, and shut well in. Called vac truck.		
Describe Area Affected and Cleanup Action Taken.*: M & R Trucking recovered 1.5 bbl further remedial action pending.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: <i>Joe Hernandez</i>	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By <i>Mike Benavise</i>	
Title: Production Foreman	Approved by District Supervisor:	
E-mail Address: jhernandez@linenergy.com	DEC 02 2011	Expiration Date:
Date: 11/18/2011 Phone: 575-942-9492	Conditions of Approval:	
	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

1/2/2012

2RP-960

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Friday, November 18, 2011 9:08 AM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick
Subject: Linn- Max Friess #1 Initial C-141
Attachments: Max Friess #1 Initial C-141.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,

Theresa McCracken

LINN Operating
2130 W. Bender Blvd
Hobbs, NM 88240
(575)738-1739
tmccracken@linnenergy.com