

District I
1625 N French Dr Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised March 17, 1999

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-37410

Release Notification and Corrective Action

NMLB/133639798 OPERATOR Initial Report Final Report

Name of Company Devon Energy <i>6137</i>	Contact <input type="checkbox"/> Roger Hernandez	
Address P. O. Box 250 Artesia, NM 88211	Telephone No. <input type="checkbox"/> 575-748-5238	
Facility Name Cotton Draw Unit #114	Facility Type <input type="checkbox"/> Oil Well	
Surface Owner	Mineral Owner	Lease No. <input type="checkbox"/>

LOCATION OF RELEASE

Unit Letter	Section 34	Township 24S	Range 31E	Feet from the 330	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
-------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

NATURE OF RELEASE


Type of Release Oil	Volume of Release 40 BO	Volume Recovered <input type="checkbox"/> 30 BO
Source of Release Separator	Date and Hour of Occurrence 11-11-11 9 00 AM	Date and Hour of Discovery <input type="checkbox"/> 11-11-11 9 00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM (Jim Amos - Carlsbad) OCD (Mike Bratcher - Artesia)	
By Whom? <input type="checkbox"/> Roger Hernandez	Date and Hour <input type="checkbox"/> BLM - 11/11/11 11 40 AM <input type="checkbox"/> OCD - 11/11/11 11 50 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully *

N/A

Describe Cause of Problem and Remedial Action Taken *

Separator malfunctioned - mechanical device broke resulting in high level equipment sending fluid out gas lines resulting in malfunction over gas outlet control device Vented gas and liquid to open top tank resulting in spill Filled tanks with fluid/overspray



Describe Area Affected and Cleanup Action Taken *

Area impacted was 40'x60', called vacuum truck to pickup fluid

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature <i>Adrienne Verkler</i>	OIL CONSERVATION DIVISION	
Printed Name Adrienne Verkler	Approved by <i>[Signature]</i>	Signed By <i>[Signature]</i>
Title Field Tech-II	Approval Date DEC 02 2011	Expiration Date
Date November 14, 2011 Phone (575) 748-0174	Conditions of Approval.	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**
1/2/2012

2RP-962