


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nmlb 1133641464

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	COG OPERATING LLC <i>219137</i>	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No	432-230-0077
Facility Name	RJ Unit #134	Facility Type	Flowline

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-34573
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	27	17S	29E					Eddy

Latitude 32.80554 Longitude 104.06587

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	4bbls oil 6bbls produced water	Volume Recovered	2bbls oil 3bbls produced water
Source of Release	Flowline	Date and Hour of Occurrence	11/11/2011	Date and Hour of Discovery	11/11/2011 3:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			
If a Watercourse was Impacted, Describe Fully *					
Describe Cause of Problem and Remedial Action Taken.*					
A hole developed in the flowline on the west side of the pad location. The bad joint of flowline has been replaced and returned into service.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 10bbls of produced fluid was release from the hole in the flowline and we were able to recover 5bbls with a vacuum truck. The fluid traveled from the west side of the pad north into the pasture and gathered in an area of 20' x 30'. The pasture area has had micro-blaze applied and all standing fluid has been recovered. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	
Title:	HSE Coordinator	Approval Date:	DEC 02 2011
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	11/22/2011	Phone:	432-212-2399
		Conditions of Approval	Attached <input type="checkbox"/>
		Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

* Attach Additional Sheets If Necessary

1/2/2012

JRP-963

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Tuesday, November 22, 2011 10:20 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov; Gregston, Terry G
Subject: C-141 Initial Report - RJ Unit #134 Flowline
Attachments: img-Y22121620-0001.pdf

Please see attached the C-141 Initial Report for a release that occurred on 11/11/2011.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.