


District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit Copy to appropriate District Office in accordance with 19 15 29 NMAC

Release Notification and Corrective Action

NMLB/133940457 OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Turner B North Battery- Turner B 95	Facility Type: Water flood
Surface Owner: BLM	Mineral Owner: BLM
API No.: 3001526612	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	20	17S	31E	2610	S	1000	W	Eddy

Latitude: 32° 49' 11.5" Longitude: -103° 53' 50.1"

NATURE OF RELEASE

Type of Release Produced Water / Oil	Volume of Release 14 / 1	Volume Recovered 9 / 0 5
Source of Release Steel Pipeline	Date and Hour of Occurrence 11/3/2011 7 15am	Date and Hour of Discovery 11/3/2011 7 30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M Bratcher- NM OCD / T Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 11/3/2011 9 00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully *		
Describe Cause of Problem and Remedial Action Taken * 2" steel flow line was buried under fire wall and was not wrapped with tape. The line was in very poor condition and already had a couple of repair clamps on it. Line only had 45 psi on it, but a weak spot in the line gave out.		
Describe Area Affected and Cleanup Action Taken * Remedial action pending		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <i>Joe Hernandez</i>	OIL CONSERVATION DIVISION	
Printed Name Joe Hernandez	Signed By <i>Mike Bratcher</i> Approved by District Supervisor	
Title. Production Foreman	Approval Date DEC 05 2011	Expiration Date
E-mail Address jhernandez@linenergy.com	Conditions of Approval	Attached <input type="checkbox"/>
Date 11/18/2011 Phone 575-942-9492	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

* Attach Additional Sheets If Necessary

1/5/2012

2 RP-965

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@lennenergy.com]
Sent: Monday, November 28, 2011 7:44 AM
To: Bratcher, Mike, EMNRD, Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick
Subject: Linn- Turner B North Batt- Initial C-141
Attachments: Turner B North Batt. Initial C-141.pdf

Please find attached the C-141 for the above referenced location.

Thank you,

Theresa McCracken

LINN Operating
2130 W. Bender Blvd
Hobbs, NM 88240
(575)738-1739
tmccracken@lennenergy.com