


District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

nmlb1133942446 OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Joe Hernandez
Address 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name Skelly Unit # 134	Facility Type: Production

Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001522268
--------------------	--------------------	---------------------

LOCATION OF RELEASE

Unit Letter E	Section 27	Township 17S	Range 31E	Feet from the 1860	North/South Line N	Feet from the 660	East/West Line W	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	----------------------	---------------------	----------------

Latitude: 32 51' 3.6" Longitude: 103 52' 3.8"

NATURE OF RELEASE

Type of Release Oil / Water	Volume of Release 18 / 1	Volume Recovered 15 / 0
Source of Release Poly flowline	Date and Hour of Occurrence 11/18/2011 1 30pm	Date and Hour of Discovery 11/18/2011 2 00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M Bratcher - NM OCD / Terry Gregston - BLM	
By Whom? Joe Hernandez	Date and Hour 11/22/2011 11 30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully *		
Describe Cause of Problem and Remedial Action Taken * 3" poly flowline popped at fuse		
Describe Area Affected and Cleanup Action Taken * Vacuum truck picked up standing fluid Further remedial action pending		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature <i>Joe Hernandez</i>	OIL CONSERVATION DIVISION	
Printed Name Joe Hernandez	Signed By <i>M. Bratcher</i> Approved by District Supervisor	
Title Production Foreman	Approval Date DEC 05 2011	Expiration Date
E-mail Address jhernandez@linenergy.com	Conditions of Approval Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date 11/28/2011 Phone 575-942-9492	<i>1/5/2012</i>	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:

2 RP-966

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Monday, November 28, 2011 8:09 AM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick
Subject: Linn- Skelly 134- Initial C-141
Attachments: Skelly 134 C-141 Initial.pdf

Please find attached the C-141 for the above referenced location

Thank you,

Theresa McCracken

LINN Operating
2130 W. Bender Blvd
Hobbs, NM 88240
(575)738-1739
tmccracken@linnenergy.com