

District I
1625 N. French Dr. Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
NOV 29 2011
NMOCD ARTESIA

Form C-14
Revised October 10, 200
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nMLB/1134057565 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Harper State Tank Battery	Facility Type	Tank Battery

Surface Owner State _____ Mineral Owner _____ Lease No. (API#) 30-015-30831

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	16	17S	30E					Eddy

Latitude 32 49 728 Longitude 103 58.150

NATURE OF RELEASE

Type of Release	Produced fluids	Volume of Release	2bbls oil 8bbls produced water	Volume Recovered	1bbls oil 6bbls produced water
Source of Release	Water transfer line	Date and Hour of Occurrence	11/21/2011	Date and Hour of Discovery	11/21/2011 4:30 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully *



Describe Cause of Problem and Remedial Action Taken *

The water transfer line leaked inside the facility. The line has been repaired and returned to service

Describe Area Affected and Cleanup Action Taken *

Initially 10bbls of produced fluid were released from the water transfer line and we were able to recover 7bbls with a vacuum truck. The entire release was contained inside the facility walls. The spill dimensions measured 3' x 70'. The spill area has been excavated and the contaminated soil has been hauled to disposal. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the OCD for approval prior to any significant remediation work

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature		OIL CONSERVATION DIVISION	
Printed Name	Josh Russo	Signed By  Approved by District Supervisor.	
Title	HSE Coordinator	Approval Date	DEC 07 2011
E-mail Address	jrusso@conchoresources.com	Expiration Date	
Date: 11/29/2011	Phone: 432-212-2399	Conditions of Approval.	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 1/7/2012**

2RP-968

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Tuesday, November 29, 2011 2:02 PM
To: Bratcher, Mike, EMNRD
Cc: Tavarez, Ike; Dorey, Kim
Subject: Harper State Tank Battery
Attachments: img-Y29150359-0001.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at the Harper State Tank Battery.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.