


District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit Copy to Appropriate District Office in accordance with 19 15 29 NMAC

**Release Notification and Corrective Action**

*nMLB 1134136889* **OPERATOR**  Initial Report  Final Report

Name of Company Linn Operating <i>269324</i>	Contact Joe Hernandez
Address 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name Turner B North # 106	Facility Type Water Flood
Surface Owner: BLM	Mineral Owner BLM
API No. 3001526706	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	17	17S	31E	15	S	1305	E	Eddy

Latitude: 32° 49' 38.5" Longitude: -103° 53' 15 2"

**NATURE OF RELEASE**

Type of Release Produced Water / Crude Oil	Volume of Release 7 / 4	Volume Recovered 1 / 3
Source of Release Poly Pipeline	Date and Hour of Occurrence 11/28/2011 7 30am	Date and Hour of Discovery 11/28/2011 8 00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher - NM OCD / Terri Gregston -BLM	
By Whom? Joe Hernandez	Date and Hour 11/29/11 2 55pm / 11/28/11 2 00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully *		
Describe Cause of Problem and Remedial Action Taken * Fuse from transition to flow line came apart There well no plugs in flowline and it did not pressure up Continues to maintain 40 psi on flow line		
Describe Area Affected and Cleanup Action Taken * Remedial action pending		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature <i>Joe Hernandez</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name Joe Hernandez	Signed By <i>M. Bratcher</i> Approved by District Supervisor	
Title Production Foreman	Approval Date DEC 07 2011	Expiration Date
E-mail Address jhernandez@linenergy.com	Conditions of Approval	Attached <input type="checkbox"/>
Date: 12/01/2011 Phone: 575-942-9492		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 1/7/2012**

*2RP-970*

**Bratcher, Mike, EMNRD**

---

**From:** Theresa McCracken [TMcCracken@linnenergy.com]  
**Sent:** Thursday, December 01, 2011 8:55 AM  
**To:** Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)  
**Cc:** Daniel Frick  
**Subject:** Linn- Turner B North #106 C-141 Initial  
**Attachments:** Turner B North # 106 C-141 Initial.pdf

Please find attached the C-141 for the above referenced location.

Thank you,

*Theresa McCracken*

**LINN Operating**  
2130 W. Bender Blvd  
Hobbs, NM 88240  
(575)738-1739  
[tmccracken@linnenergy.com](mailto:tmccracken@linnenergy.com)