


District I
1625 N French Dr, Hobbs, NM 88240
District II
811 S 1st Street, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NMB1134139502 OPERATOR Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 105 S 4 TH Street	Telephone No 575-748-1471	
Facility Name Cigarillo SWD #1	API Number 30-015-21643	Facility Type Salt Water Disposal Facility
Surface Owner State	Mineral Owner State	Lease No. L-4679

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	36	23S	27E	1980'	North	1980'	East	Eddy

Latitude 32.26322 Longitude 104.14136

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 B/PW	Volume Recovered 5 B/PW
Source of Release Lid on top of filter wouldn't secure	Date and Hour of Occurrence 11/23/2011, AM	Date and Hour of Discovery 11/23/2011; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully * N/A		
Describe Cause of Problem and Remedial Action Taken.* The lid on top of the filter housing wouldn't secure Roustabout crew was called to fix lid.		
Describe Area Affected and Cleanup Action Taken * An approximate area of 12 5' X 7' (all released water was contained on pad) The housing lid was repaired, all produced water was scraped up immediately by a backhoe that was on location. Depth to Ground Water: 50-99' (approximately 67', Section 35, T23S-R27E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on amount of water released and that is was immediately scraped up by backhoe, Yates Petroleum Corporation requests closure.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations		
Signature: <u>Amber Cannon</u>	OIL CONSERVATION DIVISION	
Printed Name Amber Cannon	Signed By <u>Mike Bernice</u> Approved by District Supervisor	
Title: Environmental Regulatory Agent	Approval Date <u>DEC 07 2011</u>	Expiration Date <u>N/A</u>
E-mail Address: <u>acannon@yatespetroleum.com</u>	Conditions of Approval <u>N/A</u> <u>Final</u>	Attached <input type="checkbox"/>
Date: Friday, December 02, 2011 Phone: 575-748-4111	2RP- 971	

* Attach Additional Sheets If Necessary

2RP-971

Bratcher, Mike, EMNRD

From: Amber Cannon [ACannon@yatespetroleum.com]
Sent: Friday, December 02, 2011 8:40 AM
To: Bratcher, Mike, EMNRD
Subject: Emailing: 20111202_083859.pdf
Attachments: 20111202_083859.pdf

Mike,

Please find attached an Initial/Final C-141 for a release that occurred at the Cigarillo SWD #1 on 11/23/2011.

Thanks,
Amber Cannon
Yates Petroleum Corporation

The message is ready to be sent with the following file or link attachments:

20111202_083859.pdf

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.