


District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nMLB1135453652 OPERATOR Initial Report Final Report

Name of Company: Linn Operating <u>269324</u>	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: JL Keel A Battery - JL Keel A #9	Facility Type: Tank Battery
Surface Owner: BLM	Mineral Owner: BLM
API No.: 3001505097	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	7	17S	31E	1980	N	1980	E	Eddy

Latitude: 32° 51' 2.2" Longitude: -103° 54' 24.2"

NATURE OF RELEASE

Type of Release: Produced water / Oil	Volume of Release: 150 / 5	Volume Recovered: 145 / 3
Source of Release: Tank	Date and Hour of Occurrence: 12/5/2011 8am	Date and Hour of Discovery: 12/5/2011 8:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher- NM OCD / Terry Gregston- BLM	
By Whom? Joe Hernandez	Date and Hour 12/13/2011 3pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Arrived at battery. Water tank overflowing. Electrical line fuse down. Alarm failure. Wells shut in and vacume trucks called. Spill was contained inside secondary containment. Electritions refuse line and transfer pump put back on. Alarm failure checked by electritions.		
Describe Area Affected and Cleanup Action Taken.*: Kenemore / Basic Trucking Remedial action pending		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By <u>Mike Bratcher</u> Approved by District Supervisor:	
Title: Production Foreman	Approval Date: DEC 20 2011	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/15/2011 Phone: 575-942-9492	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	

* Attach Additional Sheets If Necessary

1/20/2012

2RP-984

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Monday, December 19, 2011 8:44 AM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick
Subject: Linn- JL Keel A Battery Initial C-141
Attachments: JL Keel A Battery Initial C-141.pdf

Please find attached the Initial C-141 for the above referenced location.

Thank you,

Theresa McCracken

LINN Operating
2130 W. Bender Blvd
Hobbs, NM 88240
(575)738-1739
tmccracken@linnenergy.com