

District I
1625 N French Dr. Hobbs, NM 88240
District II
811 S First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <i>B.C. operating</i>	Contact <i>Jerry Livingston</i>
Address <i>P.O. Box 50820</i>	Telephone No. <i>432-464-3189</i>
Facility Name <i>South Langley Jal Trunk Line</i>	Facility Type <i>Flowline</i>

Surface Owner	Mineral Owner	API No. <i>30-025-12108</i>
---------------	---------------	-----------------------------

LOCATION OF RELEASE *API# FROM NEAREST WELL: MARY E-WILLS A FEDERAL 002*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>SW14 SW14</i>	<i>18</i>	<i>25S</i>	<i>37E</i>					<i>Lea County</i>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>Produced water + oil</i>	Volume of Release <i>10 BBL</i>	Volume Recovered <i>3 BBL</i>
Source of Release <i>Flowline Leak</i>	Date and Hour of Occurrence <i>10-18</i>	Date and Hour of Discovery <i>10-18</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>2:53 p.m.</i>	

By Whom? <i>N/A</i>	Date and Hour
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse

If a Watercourse was Impacted, Describe Fully.*
** None*

Describe Cause of Problem and Remedial Action Taken.* *Flowline on west side of Hwy 18 blew out causing 10 BALS of fluid to flow into pasture area. 3 BALS was recovered and flowline was repaired. Contaminated soil will be excavated and hauled to disposal.*

Describe Area Affected and Cleanup Action Taken.* *Pasture area west side of Hwy 18 was affected - area was dug out and line was fixed. Area will be excavated and samples will be taken. All contamination will be hauled to landfill for disposal.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Juan F. Abalos</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Juan F. Abalos</i>	ENV ENGINEER: Approved by Environmental Specialist: <i>Jeff Lebrun</i>	
Title: <i>Pumper</i>	Approval Date: <i>10/21/11</i>	Expiration Date: <i>12/21/11</i>
E-mail Address: <i>juanabalos35@yahoo.com</i>	Conditions of Approval: <i>SUBMIT FINAL C-141 BY 12/21/11</i>	Attached <input type="checkbox"/> <i>IRP-10-11-2747</i>
Date: <i>10-19-11</i>	Phone: <i>(575)441-1733</i>	

* Attach Additional Sheets If Necessary

JAN 25 2012