

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-25330

Release Notification and Corrective Action

nMLB/203337597

OPERATOR

Initial Report Final Report

Name of Company BOPCO, L.P. BERCO 1801	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Bass 3 Federal Battery #1	Facility Type: E&P

Surface Owner Federal	Mineral Owner Federal	Lease No. LC-060853A
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	3	22S	28E	230	South	1090	East	Eddy

Latitude N 32.415370 Longitude W 104.06990

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 20 Bbls of Crude oil	Volume Recovered: 5 bbls
Source of Release: Oil production tank #113678	Date and Hour of Occurrence 1/3/12 time unknown	Date and Hour of Discovery 1/3/12 2:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOC emergency #104	
By Whom? Tony Savoie	Date and Hour 1/4/12 2:37 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

RECEIVED
 JAN 17 2012
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.* A hole was discovered in the bottom of the south oil production tank. The tank was taken out of service the day of discovery. The tank was cleaned, repaired and coated on 1/6/12.

Describe Area Affected and Cleanup Action Taken.*The crude oil was contained inside the earthen containment. A vacuum truck recovered approximately 5 bbls of crude oil, the remainder of the spill soaked into the ground. The total area affected by this release measured approximately 2430 sq. ft. During the site assessment it was noted that were areas inside the containment that were obviously impacted from previous releases of crude oil and produced water. An air rotary rig is scheduled for 1/9/12 to try and define the horizontal and vertical extent of the release. The Site remediation for the produced water and crude oil spill will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor <i>[Signature]</i>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: FEB 02 2012	Expiration Date:
E-mail Address: TAsavoie@BassPet.com	Conditions of Approval:	
Date: 1/9/12 Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	
	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

3/2/2012

JPA-996