

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JAN 16 2012
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nMLB1204149632 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Dogwood Federal	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No. (API)#	30-015-32927
					NMNM-94594



LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	25	17S	27E					Eddy

Latitude 32 48.245 Longitude 104 14.115

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	105bbbs	Volume Recovered	100bbbs
Source of Release	Water tank	Date and Hour of Occurrence	01/03/2012	Date and Hour of Discovery	01/03/2012 8:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD Jim Amos- BLM Terry Gregston- BLM		
By Whom?	Josh Russo	Date and Hour	01/04/2012 10:54 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Wells were turned off due to problems with water haulers and when the wells were turned back on the water haulers were not notified in time.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 105bbbs were released and we were able to recover 100bbbs with a vacuum truck. All of the fluid was contained inside the walls of the facility. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present the NMOCD/BLM with a work plan for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	
Title:	HSE Coordinator	Approval Date:	FEB 10 2012
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	01/16/2012	Phone:	432-212-2399

Conditions of Approval:
Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 3/10/12**

Attached

ZRP-1002

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Monday, January 16, 2012 4:06 PM
To: Bratcher, Mike, EMNRD; Amos, James A; Terry_Gregston@blm.gov
Cc: Tavarez, Ike; Dorey, Kim; Franklin, Tom K.
Subject: C-141 - DOGWOOD FEDERAL TB
Attachments: DOGWOOD FEDERAL TANK BATTERY -- DATE OF RELEASE -- 01-03-2012.pdf

Please see attached the C-141 Initial Report for a release at the Dogwood Federal TB. This spill is in the same facility as the prior Dogwood Federal Tank Battery spill that we had already assessed and made a work plan for.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system.
Thank you

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Wednesday, January 04, 2012 9:54 AM
To: Bratcher, Mike, EMNRD; Amos, James A; Terry_Gregston@blm.gov
Cc: Tavares, Ike; Grubbs, Robert
Subject: Concho - Release Notification - Dogwood Federal TB

Please see below the detailed description of a release:

On 1-3-2012, the water tank ran over on the Dogwood Fed. #1 battery. The spill was caused by a miscommunication between the lease operator and the water hauling company. 105bbbls of produced water was released into the dike. 100bbbls of produced water was recovered and hauled to a disposal site.

We have to discuss due to the fact that we have an approved work plan for this location based on a previous spill. We were planning to start this remediation within the next two weeks.

GPS, legal description, and driving directions below:

N 32* 48.245 W 104* 14.114

Dogwood Federal #1
2310' FNL & 1650' FWL
Sec.25-T17S-R27E
Eddy Co.
NMNM-94594, API #30-015-32927

From US 82, T/S on CR 204 .25mi, T/E to location.

Thank you,

Joshua Russo
HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.