

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
JAN 27 2012  
**NMOCD ARTESIA**

Form C-141  
Revised March 17, 1999  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**30-015-32595** Release Notification and Corrective Action

Name of Company <b>CHEVRON</b> <b>4323</b>		Contact <b>David Pagano</b>
Address <b>56 Texas Camp Road, Lovington NM 88260</b>		Telephone No. Office: <b>575-396-4414 ext 275</b> Cellular: <b>505-787-9816</b>
Facility Name: <b>Skelly Unit 936</b>		Facility Type: <b>Producing Well</b>

Surface Owner: <b>Federal</b>	Mineral Owner	Lease No. <b>NM-98122</b>
-------------------------------	---------------	---------------------------

LOCATION OF RELEASE-API # **30-015-32595**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	21	17.0S	31E					Eddy

NATURE OF RELEASE

Type of Release <b>Crude Oil and produced Water Spill</b>	Volume of Release <b>8.6bbls fluid</b>	Volume Recovered
Source of Release : <b>Flow Line</b>	Date and Hour of Occurrence <b>01/24/12 10:45</b>	Date and Hour of Discovery <b>01/24/12 11:00</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mr. Leking via voicemail</b>	
By Whom? <b>David Pagano</b>		
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken \*

It appears someone drove around wellhead and snagged out poly gas line, causing 8.6bbl fluid spill, mostly oil with a small amount of produced water. Chemical rep notified pumper of spill to land at 10:45 and pumper immediately drove to well and shut well in to contain release. Well shut in at approx 11:00AM.

Describe Area Affected and Cleanup Action Taken.\*

Approx 8.6bbbs of fluid mostly oil spilled on pad and worked its way to the road as well as foot wide path that ran into the pasture. Vacuum truck vacuumed up standing liquid on pad and road. Chevron has received Archeological/wildlife clearance from BLM. Backhoe will excavate contaminated soil on pad and road and contaminated soil will be taken offsite for disposal. Spray off of pad into the pasture will be remediated by knocking off fluids from vegetation using biodegradable soap and then we are looking at using micro blaze to remediated contaminated soil. Surface sample will be taken tomorrow to determine level of chlorides in order to evaluate potential effectiveness of micro blaze for pasture/off pad remediation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <b>David Pagano</b>	Signed By 	
Title: <b>Health &amp; Environmental Specialist</b>	Approved by <b>District Supervisor.</b>	
Date: <b>01/25/12</b> Phone: <b>505-787-9816</b>	Approval Date: <b>FEB 13 2012</b>	Expiration Date:
Conditions of Approval:		Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 3/13/2012**

**2RP-1010**

## Bratcher, Mike, EMNRD

---

**From:** Pagano, David (David.Pagano) [David.Pagano@chevron.com]  
**Sent:** Friday, January 27, 2012 8:46 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** FW: SKU 936 Spill to Land C-141  
**Attachments:** 20120124 C-141 SKU 936 spill.pdf

Mr. Bratcher,

We had a spill at our Skelly 936 well on Wednesday and I incorrectly sent the C-141 to Mr. Leking. He just called and informed that that the OCD District 2 Office cover Eddy County. Here is the C141. Currently we have vacuumed up all the fluids and excavated all the visibly contaminated soil on the pad and the road. I had coordinated with Mr. Leking to go take confirmation samples this morning at around 9:00AM. Please let me know if you are ok with me taking the sample today.

Regards,

### **David A. Pagano**

*MCA Health & Environmental Specialist (Oil Area – Vacuum/Buckeye, Dollarhide & Sundown)*

56 Texas Camp. Rd., Lovington, NM 88260

☎ Phone: 575-396-4414 x275

☎ Cell: 505-787-9816

☎ Fax: 575-396-6913

[dpgn@chevron.com](mailto:dpgn@chevron.com)

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."

---

**From:** Pagano, David (David.Pagano)  
**Sent:** Thursday, January 26, 2012 7:28 AM  
**To:** Pagano, David (David.Pagano); 'Leking, Geoffrey R, EMNRD'  
**Cc:** DeLeon, Josepha; Moschetti, Nick (NMOS)  
**Subject:** SKU 936 Spill to Land C-141

Geoffrey,

Here is the initial C-141 report for the SKU 936 spill to land that occurred on 12/24/12. I will provide you with the sample results once I have them and let you know if our local remediation was successful or if this will be turned over to Chevron EMC. Also, note that this is BLM land and we will work within their guidance on remediation for the contamination that occurred off the pad/road. Please let me know if you have any questions or need any additional information.

Regards,

### **David A. Pagano**

*MCA Health & Environmental Specialist (Oil Area – Vacuum/Buckeye, Dollarhide & Sundown)*

56 Texas Camp. Rd., Lovington, NM 88260

☎ Phone: 575-396-4414 x275

☎ Cell: 505-787-9816

☎ Fax: 575-396-6913

[dpgn@chevron.com](mailto:dpgn@chevron.com)

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."