


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC

**Release Notification and Corrective Action**

nMLB: 204638693 OPERATOR  Initial Report  Final Report

Name of Company: Linn Operating 269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: JL KEEL A #30 - JL KEEL B #30	Facility Type: Gas Central Tank Battery
Surface Owner: BLM	Mineral Owner: BLM
API No.: 3001521460	

**LOCATION OF RELEASE**

Unit Letter O	Section 06	Township 17S	Range 31E	Feet from the 430	North/South Line South	Feet from the 2250	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.85744 Longitude: -103.90692

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release 72	Volume Recovered: 10
Source of Release: Pipeline	Date and Hour of Occurrence: 10/21/2011 5am	Date and Hour of Discovery: 10/21/2011 5:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 10/21/2011	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: Injection plant lost pressure on line and shut down. Alarm system called and went out to plant. Arrived and shut in line and started looking for leak. Leak was located at a field valve and was on main trunk line. All wells on line were shut in and vacuume truck was called to pick up spill.

Describe Area Affected and Cleanup Action Taken.\* : Approximately 10 bbls were picked up. Vacuum truck also tied on to line and drained to prevent more spilling as line drained.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Joe Hernandez	Signed By Approved by District Supervisor.	
Title: Production Foreman	Approval Date: FEB 15 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	Attached <input type="checkbox"/>
Date: 02/02/2012 Phone: 575-942-9492	<u>3/15/2012</u>	

\* Attach Additional Sheets If Necessary

2RP-1022

**Bratcher, Mike, EMNRD**

---

**From:** Theresa McCracken [TMcCracken@linenergy.com]  
**Sent:** Thursday, February 02, 2012 4:08 PM  
**To:** Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)  
**Cc:** Daniel Frick  
**Subject:** Linn- Initial C-141 "JL Keel A 30"- JL KEEL B #30  
**Attachments:** Keel A 30 - JL KEEL B # 30.pdf

Please find attached the initial C-141 for the above referenced location.

*Theresa McCracken*

**LINN Operating**

2130 W. Bender Blvd

Hobbs, NM 88240

(575)738-1739

[tmccracken@linenergy.com](mailto:tmccracken@linenergy.com)