

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 28 2011

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Centurion Pipeline, LP	Contact: Becky Moore, Compliance Coordinator
Address: PO BOX 51790 Midland, TX 79710	Telephone No.: 432-686-6805
Facility Name: Brahmey Gathering System	Facility Type: Sweet Crude Oil Pipeline
Surface Owner: Wesley Harris	Mineral Owner: _____ Lease No.: _____

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County	LEA
M	4	13S	38E						

Latitude 33° 12.847' Longitude 103° 06.603'

NATURE OF RELEASE

Type of Release: Sweet Crude Oil	Volume of Release: 4.5 bbls	Volume Recovered: -0-
Source of Release: Pipeline	Date and Hour of Occurrence: 9/25/11	Date and Hour of Discovery: 9/25/11
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD: Geoffrey R. Leking	
By Whom? Mike Stubblefield	Date and Hour: 9/25/11	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Internal corrosion of 8" pipeline caused a leak on the 8" Brahmey Gathering System. Emergency response included immediate shut-in of the pipeline to stop leak and pipeline was replaced on 9/26/11. A contract remediation company was contacted and is currently in process of delineating to determine appropriate clean up actions.		
Describe Area Affected and Cleanup Action Taken.* The impacted soil excavated for the pipeline repairs is being sent to Gandy Land Fill on 9/28/11. Talon/LPB has been contracted to complete site assessment and work plan activities.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Vaibhava Romero for R. Moore</i>	ENV. SPECIALIST	
Printed Name: R.A. Moore	Approved by District Supervisor: <i>Geoffrey R. Leking</i>	
Title: Compliance Coordinator / HES Specialist	Approval Date: 9/29/11	Expiration Date: 11/29/11
E-mail Address: Rebecca.Moore@ony.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 9/27/11 Phone: 432-978-8067 cell	C-141 BY 11/29/11.	IRP-4-12-2794

* Attach Additional Sheets If Necessary

APR 10 2012