


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nMLB1209641725 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Big George State Tank Battery	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-26340
---------------	-------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	12	17S	28E					Eddy

Latitude 32 50.852 Longitude 104 07.600

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	8bbls	Volume Recovered	7bbls
Source of Release	1/4" nipple on discharge side of water pump	Date and Hour of Occurrence	03/12/2012	Date and Hour of Discovery	03/12/2012 6:30 a.m
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The 1/4" nipple on the discharge side of the water pump failed do to vibration and corrosion. The 1/4" nipple has been replaced.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 8bbls of produced water were released from the water pump and we were able to recover 7bbls with a vacuum truck. The spill area measured roughly 10' x 60' inside the tank battery with an area of overspray measuring roughly 30' x 50' on location outside of the tank battery. All free fluids have been picked up and the overspray area has been scraped with a backhoe. This spill area is identical to the spill from 07/27/2011. BBC will handle the remediation and closure of this release as well as the 07/27/2011 spill event.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	
Title:	HSE Coordinator	Approval Date:	APR 05 2012
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	03/26/2012	Phone:	432-212-2399

Conditions of Approval:
Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: MAY 5, 2012**

Attached

2RA-1079

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Monday, March 26, 2012 10:09 AM
To: Bratcher, Mike, EMNRD
Cc: Cliff P. Brunson; Ken Swinney
Subject: C-141 Initial Report - Big George State Tank Battery
Attachments: img-326114731-0001.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release the occurred on 03/12/2012 at our Big George State Tank Battery. BBC will be handling the remediation and closure report for this release.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.