

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-27162

Release Notification and Corrective Action

NMLB/209648301 OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	Chancey Summers
Address	1017 W. Stanolind Road; Hobbs, NM 88240	Telephone No.	575-397-8216
Facility Name	AMAX 24 #8 CTB	Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		Lease No.	
---------------	-----	---------------	--	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	24	23S	31E					Eddy County, NM

Latitude 32.28895 Longitude 103.73888

NATURE OF RELEASE

Type of Release	Oil & Produced water	Volume of Release	30 bbls	Volume Recovered	0 bbls
Source of Release	End Cap Leak on rental Frac Tank	Date and Hour of Occurrence	01/24/2012 @ 9:35 a.m.	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Chancey Summers	Mike Bratcher-OCD, James Amos- BLM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour 02/16/2012 @ 11:33 a.m.			
If YES, Volume Impacting the Watercourse.					


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A failure of the end cap on a frac tank caused 30 bbls of oil and produced water to leak. The end cap was replaced.

Describe Area Affected and Cleanup Action Taken.*

Remediate to NMOCD guidelines.



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Signed By:	
Title: HES Specialist	Approved by District Supervisor:	
E-mail Address: chancey_summers@oxy.com	Approval Date: APR 05 2012	Expiration Date:
Date: 3-22-12 Phone: (575) 397-8216	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 5/5/2012	Attached <input type="checkbox"/>


* Attach Additional Sheets If Necessary

2RP-1080



PHONE (575) 397-6388 • FAX (575) 397- 0397 • 1324 W. MARLAND • P.O. BOX 805 • HOBBS, NM 88241-0805
E-MAIL: cbrunson@bbcinternational.com

March 22, 2012



Mr. Mike Bratcher
New Mexico Oil Conservation Division
811 S. First Street
Artesia, NM 88210

Re: Oxy Initial C-141 Notifications for AMAX 24 #8 CTB, Cypress 34 Federal 4H, and
Riverbend B-11 Battery

Dear Mr. Bratcher:

On behalf of Oxy USA, BBC International, Inc. is pleased to enclose the initial C-141 notifications for the above referenced sites for your records.

Please let us know if you require any additional information.

Sincerely,

A handwritten signature in black ink that reads "Cliff P. Brunson". The signature is written in a cursive style with a long horizontal flourish at the end.

Cliff P. Brunson
President

Enclosures

Bratcher, Mike, EMNRD

From: Chancey_Summers@oxy.com
Sent: Thursday, February 16, 2012 11:33 AM
To: Chancey_Summers@oxy.com; Dusty_Wilson@oxy.com; Bratcher, Mike, EMNRD; jamos@blm.gov
Cc: cbrunson@bbcinternational.com; kswinney@bbcinternational.com
Subject: Amax 24 # 8 and Cypress 34 Federal 4H

All, this email is to inform you of a Reportable leak that Oxy Permian had at the Amax 24 # 8 on January 24, 2012 . Total release was 30 bbls of oil and water mix, with 0 recovered. The leak was due to failure of end cap on rental Frac Tank. Battery is located in Section 24, Township 23s, and Range 31E of Eddy County. Oxy will be performing some initial clean up of the surface soils and gathering soil samples to be tested for impact in the near future. A C-141 will follow.

Oxy had an additional reportable leak at the Cypress 34 Fed 4H on January 30, 2012 . Total release was 45 bbls of oil and water mix, with 0 recovered. The leak was due to overfilling of tank during flowback . Battery is located in Unit D Section 34, Township 23s, and Range 29E of Eddy County. Oxy will be performing some initial clean up of the surface soils and gathering soil samples to be tested for impact in the near future. A C-141 will follow. If you have any questions feel free to reply.

Thank You

C.J. Summers

HES Specialist

Cell # 575-631-9436

Office # 575-397-8216

Chancey_Summers@oxy.com

"When the blind lead the blind, get out of the way!"