


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nMLB 1210938738 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Jenkins B Federal Water Flood (Northwest Central)	Facility Type	Skim Tank

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-21945
					closest well location

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	20	17S	30E					Eddy

Latitude 32 49.813 Longitude 103 59.736

NATURE OF RELEASE

Type of Release	Produced water / Oil	Volume of Release	3bbls oil 17bbls pw	Volume Recovered	3bbls oil 15bbls pw
Source of Release	Skim tank	Date and Hour of Occurrence	03/23/2012	Date and Hour of Discovery	03/23/2012 11:30 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully *					
Describe Cause of Problem and Remedial Action Taken.*					
Due to a rush of fluid from a new well and a plugged strainer at our Texaco BE #8 Injector the skim tank overflowed. The strainer at the Texaco BE #8 Injector has been cleaned out.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls were released from the skim tank and we were able to recover 18bbls with a vacuum truck. The spill area measures 20' x 20' around the skim tank. The release was contained on the location. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD/BLM for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Signed By <i>Mike Beaman</i>	
Title:	HSE Coordinator	Approved by District Supervisor:	
E-mail Address:	jrusso@conchoresources.com	Approval Date:	APR 18 2012
Date:	04/02/2012	Expiration Date:	
Phone:	432-212-2399	Conditions of Approval:	Attached <input type="checkbox"/>

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 5/18/2012**

2RA-1094

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Monday, April 02, 2012 2:48 PM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov); Jim Amos office (jamos@blm.gov)
Cc: Tavarez, Ike; Dorey, Kim; Franklin, Tom K.
Subject: C-141 Initial Report - Jenkins B Federal Water Flood Skim Tank
Attachments: JENKINS B WATER FLOOD SKIM TANK -- DATE OF RELEASE -- 03-23-2012.pdf

Please see attached the C-141 Initial Report for a release that occurred at our Northwest Central location. We plan to take soil samples timely.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.