

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
APR 11 2012
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-28102

Release Notification and Corrective Action

NMLB 1211158154

OPERATOR

Initial Report Final Report

Name of Company BOPCO, L.P. <i>260737</i>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Poker Lake Unit #114	Facility Type E&P

Surface Owner State Of N.M.	Mineral Owner State of N.M.	Lease No. 8910000303E
-----------------------------	-----------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	36	24S	30E	1982	North	2019	West	Eddy

Latitude N 32.176120 Longitude W 103.836300

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 10 bbls produced water and 5 bbls crude oil	Volume Recovered: 0
Source of Release: 1/2" valve on the wellhead	Date and Hour of Occurrence 3/27/12 Time unknown	Date and Hour of Discovery 3/27/12 2:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A 1/2" valve on the wellhead was accidentally opened, the valve handle was removed and the valve was plugged.

Describe Area Affected and Cleanup Action Taken.* An area covering approximately 2400 sq.ft. on the caliche well pad was affected by the release, the saturated soil was scraped up and stockpiled on site. The spill will be remediated following the NMOCD guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by <i>[Signature]</i>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: APR 20 2012	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: 4/10/12 Phone: 432-556-8730	<i>5/20/2012</i>	<i>2RP-1100</i>

* Attach Additional Sheets If Necessary