


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit to appropriate District Office in accordance with 19.15.29 NMAC

**Release Notification and Corrective Action**

*nmlb1211540365* OPERATOR  Initial Report  Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly 401	Facility Type: Oil Well
Surface Owner: Federal	Mineral Owner: Federal
API No.: 3001529817	

**LOCATION OF RELEASE**

Unit Letter D	Section 28	Township 17S	Range 31E	Feet from the 1300	North/South Line North	Feet from the 60	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	---------------------	------------------------	----------------

Latitude: 32.8092438074323 Longitude: -103.883084059221

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 4	Volume Recovered: 0
Source of Release: Flowline	Date and Hour of Occurrence: 12/6/2011 7am	Date and Hour of Discovery: 12/6/2011 7:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? unknown	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Drove to location and found flowline separated, shut down well and isolated flowline. Called roustabout to repair flowline.		
Describe Area Affected and Cleanup Action Taken.* : Further remedial action pending.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Joe Hernandez</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Joe Hernandez	Signed By <i>Mike Benjamin</i> Approved by District Supervisor:	
Title: Production Foreman	APR 24 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	Attached <input type="checkbox"/>
Date: 04/09/2012 Phone: 575-942-9492	<i>5/24/2012</i>	<i>2RA-1104</i>

\* Attach Additional Sheets If Necessary

## **Bratcher, Mike, EMNRD**

---

**From:** Theresa McCracken [TMcCracken@linnenergy.com]  
**Sent:** Monday, April 09, 2012 9:50 AM  
**To:** Bratcher, Mike, EMNRD; m.burton@blm.gov  
**Cc:** Daniel Frick; Ron Ragland  
**Subject:** Linn- Skelly 401 Initial C-141 12-6-11  
**Attachments:** Skelly 401 Intial C-141 12-6-11.pdf

Please find attached in the Initial C-141 for the above referenced location.

Thank you,

*Theresa McCracken*

**LINN Operating**  
2130 W. Bender Blvd  
Hobbs, NM 88240  
(575)738-1739  
[tmccracken@linnenergy.com](mailto:tmccracken@linnenergy.com)