

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: Targa Midstream Services L.P.	Contact: Ralph England
Address: P.O. Box 1689, Lovington, NM 88260	Telephone No.: 575-396-3221
Facility Name: Saunders Plant	Facility Type: Gas Processing

Surface Owner: Dan Field Branch Ranch	Mineral Owner	Lease No.:
---------------------------------------	---------------	------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
U	3	16S	35E	929'	SOUTH	31'	WEST	LEA

Latitude: 32.946433° Longitude: -103.454091°

**NATURE OF RELEASE API # 30-025-01195**

Type of Release: Gas Release	Volume of Release: Unknown	Volume Recovered: 0
Source of Release: 20" steel pipeline	Date and Hour of Occurrence: 5-22-12 UNKNOWN	Date and Hour of Discovery: 5-22-12
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Gas pipeline leak discovered by Targa personal while performing routine line inspection. Watson Const. Co. was called out, pipeline was excavated and leak was clamped off. Site backfilled and ETNM / WEE Inc. were contacted to clean up leak.  
DEPTH TO GROUND WATER ACCORDING TO TEXACO/CHEVRON 2005 WATER DATA MAP FOR LEA COUNTY IS APPROXIMATELY 57' bgs +/-

Describe Area Affected and Cleanup Action Taken.\*

CLEAN UP ACTION: leak area was clamped off and backfilled. Targa is in the process of ordering new poly pipe for replacement of old pipe. ETNM / WEE Inc. has been contracted to perform clean up of leak area. Site will be cleaned up in accordance with NMOCD Leak Clean up standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ralph England</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ralph England	ENV SPECIALIST: ENV SUPERVISOR:	
Title: Field Supervisor	Approved by: <i>Jeff Lebing</i> District Supervisor:	
E-mail Address: REngland@targaresources.com	Approval Date: 5/29/12	Expiration Date: 7/30/12
Date: 5-25-12 Phone: (575) 396-3221	Conditions of Approval: SUBMIT FINAL C-141 BY 7/30/12	Attached <input type="checkbox"/> IRP-5-12-2816

\* Attach Additional Sheets If Necessary

MAY 30 2012